

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Contract #100

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla "D"

9. WELL NO.

16

10. FIELD AND POOL, OR WILDCAT

Tapacito Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 30, T-26N, R-3E
S.W. 1/4

12. COUNTY OR PARISH

Mio Arriba

13. STATE

New Mexico

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Southern Union Production Company

3. ADDRESS OF OPERATOR

P.O. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

910 Ft. from the South line and 805 ft. from the East line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7174 Ft. Ground Level

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Supplemental History

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Drilled 7-7/8" hole to T.D. of 3910 ft. Reached T.D. 10-19-74.
2. Ran ILS and Density logs.
3. Ran 117 joints of 4-1/2", 10.5#, casing. Landed at 3900 ft. 4-1/2" stage collar set at 2524 ft. 1st stage cemented w/228 sacks. Plug down at 5:00 P.M., 10-20-74. 2nd stage cemented w/290 sacks. Plug down at 7:30 P.M., 10-20-74.
4. Moved in completion rig 11-23-74.
5. Ran tubing and bit and drilled out stage collar at 2524 ft. Cleaned out well to P.S.T.D. of 3880 ft.
6. Pressure tested casing to 2800 psi. Test OK.
7. Ran cement bond and Correlation log.
8. Perforated Pictured Cliffs zones 2 shots/ft. from 3804 - 3828 ft. Total of 48 holes.
9. Sand water fraced perfs w/70,000# sand and 75,000 gallons water.
10. Ran 114 joints of 1-1/2", 2.9#, L.U.L. tubing. Landed at 3744 ft.
11. Well completed 11-25-74.

18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by
Jan R. Collier

TITLE Office Manager

DATE Dec. 3, 1974

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.