Ferm. 9-331 (May 1963) DEPAR	UNITED STATES TMENT OF THE INTER GEOLOGICAL SURVEY	SUBMIT IN TRIPLICATE*  (Other instructions on re- lor verse side)	Form approved. Budget Bureau No. 42-R1424.  5. LEASE DESIGNATION AND SERIAL NO.  Jicarilla Contract #151
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME  Jicarilla Apache
1.			7. UNIT AGREEMENT NAME
WELL GAS WELL OTHER			S. FARM OR LEASE NAME
2. NAME OF OPERATOR			Arizona Jicarilla "B"
Aztec Oil & Gas Comp	oany		9. WELL NO.
			#6
P. O. Drawer 570, Farmington, New Mexico 87491  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface		10. FIELD AND POOL, OR WILDCAT	
		Tapacitos Pictured Cliffs	
16	880' FSL & 1850' FEL		11. SBC., T., R., M., OR BLK. AND SURVEY OR ARBA
Se	ection 9-26N-5W	The state of the s	302121 02 222
			Section 9-26N-5W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF,			
14. PERMIT NO.	15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	12. COUNTY OR PARISH 18. STATE
14. PERMIT NO.		r, st., gr., etc.) Fround Level	Rio Arriba New Mexico
	6982' 0	round Level	Rio Arriba New Mexico
16. Check A	6982' C	round Level Nature of Notice, Report, or C	Rio Arriba New Mexico
16. Check A	Appropriate Box To Indicate I	Nature of Notice, Report, or C	Rio Arriba New Mexico Other Data DENT REPORT OF:
16. Check / NOTICE OF INT	Appropriate Box To Indicate I	Nature of Notice, Report, or C  SUBSEQUE  WATER SHUT-OFF	Rio Arriba New Mexico  Other Data  UENT REPORT OF:  REPAIRING WELL
16. Check / NOTICE OF INT TEST WATER SHUT-OFF FRACTURE TREAT	Appropriate Box To Indicate Internation to:  PULL OR ALTER CASING MULTIPLE COMPLETE	Nature of Notice, Report, or C  SUBSEQUE  WATER SHUT-OFF  FRACTURE TREATMENT	Rio Arriba New Mexico  Other Data  UENT REPORT OF:  REPAIRING WELL  ALTERING CASING
16. Check / NOTICE OF INT TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE	Appropriate Box To Indicate Internation to:  PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON*	Nature of Notice, Report, or C  SUBSEQUE  WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING	Rio Arriba New Mexico  Other Data  UENT REPORT OF:  REPAIRING WELL
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	Appropriate Box To Indicate Internation to:  PULL OR ALTER CASING MULTIPLE COMPLETE	Tround Level  Nature of Notice, Report, or C  SUBSEQUE  WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other) (Note: Report results	Rio Arriba New Mexico  Other Data  DENT REPORT OF:  REPAIRING WELL ALTERING CASING ABANDONMENT*  Spud Report  Sof multiple completion on Well
16. Check A NOTICE OF INT TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	Appropriate Box To Indicate Internation to:  PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results Completion or Recomp	Rio Arriba New Mexico  Other Data  UENT REPORT OF:  REPAIRING WELL  ALTERING CABING  ABANDONMENT®  Spud Report  X
16. Check / NOTICE OF INT  TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)  17. DESCRIBE PROPOSED OR COMPLETED OR proposed work. If well is directly nent to this work.) *	Appropriate Box To Indicate Internation to:  PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	Stround Level  Nature of Notice, Report, or C  SUBSEQUENT SHOTTURE TREATMENT SHOOTING OR ACIDIZING  (Other)  (Note: Report results Completion or Recomputed dates, and give pertinent dates, attions and measured and true vertices.	Rio Arriba New Mexico  Other Data  UENT REPORT OF:  ( REPAIRING WELL  ALTERING CASING  ABANDONMENT*  Spud Report  S of multiple completion on Well eletion Report and Log form.) , including estimated date of starting any al depths for all markers and sones perti-
16. Check / NOTICE OF INT TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)  17. DESCRIBE PROPOSED OR COMPLETED Of proposed work. If well is directly nent to this work.)*	Appropriate Box To Indicate Internation to:  PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS  OPERATIONS (Clearly state all pertine ctionally drilled, give subsurface local	WATER SHUT-OFF SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recomp nt details, and give pertinent dates, stions and measured and true vertice.	Rio Arriba New Mexico  Other Data  UENT REPORT OF:  REPAIRING WELL  ALTERING CASING  ABANDONMENT®  Spud Report  Sof multiple completion on Well letion Report and Log form.)  Including estimated date of starting any all depths for all markers and sones perti-