

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
1530' FNL, 990' FWL Sec. 2, T-26-N, R-3-W, NMPM

5. Lease Number
Jic. Contract 96

6. If Indian, All. or Tribe Name
Jicarilla Apache

7. Unit Agreement Name

8. Well Name & Number
Jicarilla 96 #6A

9. API Well No.

10. Field and Pool
Blanco MV/Gavilan PC

11. County and State
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - add Pic. Cliffs and commingle	

13. Describe Proposed or Completed Operations

11-17-93 MOL&RU. Kill well. ND WH. NU BOP. TOO H w/tbg.

11-18-93 Set CIBP @ 5400'. Load hole w/2% KCl wtr. Run CCL-CBL-GR 1400-4040'. PT 3000#/30 min, ok. Perf Pictured Cliffs 3679-3794' w/0.31" holes (17 total). Spot 1000 gal 7.5% HCl. Ran gge ring.

11-19-93 Frac w/105,000# 12/20 sand and 41,598 gal gel, 70 qual foam, and N2. Flow back after frac.

11-20-93 Blow well. Set RBP @ 3480'. Load hole w/2% KCl wtr. Ran CET log.

11-21-93 TOO H w/RBP. Ran after frac GR log. TIH to 3885'. Blow well and flow naturally.

11-22-93 Blow well. CO 4815-4840'. Stuck @ 4840'. Work stuck pipe. Ran freepoint. Cut off 12' tbg in hole. TIH w/wash pipe and jars to 3900'. Unload hole and CO to 4840'. Circ and CO to 4872'. Blow well. TOO H w/wash pipe and tbg cutoff stuck in wash pipe.

11-23-93 CO 4882-5400'. Drill out CIBP @ 5400'. CO to 6200'. Ran 2 3/8", 4.7#, J-55 tbg landed @ 6016'. F nipple @ 5971'. ND BOP. NU WH. Well commingled per Order DHC 925.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 12-23-93

(This space for Federal or State Office use)

APPROVED BY [Signature] Title Acting Area Date 2/16/94

CONDITION OF APPROVAL, if any:

INACCD