UBMIT	IN	TRIPL	ICA'	EE*	1
Other i	nstr	uctions	on	re-	<u></u> -
erse side	• )				່ ນ.

Form 9-331 (May 1963)	UNITED STATES	Other instructions on re-	Budget Bureau No. 42-R1424.  LEASE DESIGNATION AND SERIAL NO.
DEPARIM	MENT OF THE INTERIC	)R verse side)	LEASE DESIGNATION AND BEEFER NO.
G	EOLOGICAL SURVEY		NM 03.554
CUNIDDY MOT	CES AND REPORTS O	N WELLS	IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDKY NOT	als to drill or to deepen or plug bar	ck to a different reservoir.	
(Do not use this form for propose	als to drill or to deepen or plug bac TION FOR PERMIT—" for such pro-	posals.)	
1.		7	. UNIT AGREEMENT NAME
OIL GAS THER			
2. NAME OF OPERATOR		8	FARM OR LEASE NAME NEWS
Caulkins Oil	Breech CT all the		
			WELL NO.
3. ADDRESS OF OPERATOR Post Office B	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
4. LOCATION OF WELL (Report location c	0. FIELD AND POOL, OR WILDCAT		
4. LOCATION OF WELL (Report location of See also space 17 below.)	South Blanco		
At surface		<b> </b> ,	II. SEC., T., R., ME OR BEEL ANDE
			SURVEY OR ARBA
800 from South and	1100 from East	j	Section 12 26 N 36W
SOO IIOM BOUGH and			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,		12. COUNTY OB PARISH 13. STATE
	6593 Gr		Rio Arriba New Mexico
		- /	LIDAL GEORGE
16. Check A	ppropriate Box to Indicate No	ature of Notice, Report, or Otl	
NOTICE OF INTER	NTION TO:	SUBSEQUE	NT REPORT OF:
	[]		REPAIRING WELL
	PULL OR ALTER CASING	WATER SHUT-OFF	ALTERING CASING
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ABANDONMENT
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONALN
REPAIR WELL	CHANGE PLANS	(Other)	f multiple-completion on Well
(Other)		Completion or Recomplet	ion Report and Log form.
17. DESCRIBE PROPOSED OR COMPLETED OP	ERATIONS (Clearly state all pertinent	t details, and give pertinent dates, in	ncluding estimated date of starting any denths for all markers; and zones pertif.
proposed work. If well is directinent to this work.) *	onally drilled, give subsurtace locat	ions and measured and true vertical	depths for all markers and zones perti-
Spud at 11:30	) AM 6-3-76.		
Dest 11 ad 12 1	// hole to 100!	Ran 8 5/8" 24# J-5	5 casing to 100
Drifted 12 1/	4 1016 00 100 •	2% CaCl Cement C	irculated to surface.
tnen cemented	1 WILLI IZJ SACKS.	2/0 GAGI: Gement	
Plug down 4:	:00 PM 6-3-76.		
_			6 1 376 372+1 32
Tested surface	ce casing with 600	# for 30 minutes,	O-4-70 MINI HOLE
decrease in ]	pressure.		
•	•		Cho as repair to the control of the
			133128 9 AA37
			rabel olders rabel older
			정말하다 등 경우스타
		· · · · · · · · · · · · · · · · · · ·	
	CERN	the second	
	/OFI'TID	<b>\</b>	도 그 사람이 되고 있는 것이다. 그리고 있는 것이 되고 있는 것이다.
	/ ^\L\f\/I	Viert 19 107	
	/	//\ JUNI ( U 197	이 기술 발생 집 교육 생물으로 하다.
	I JIM .	~ <u> </u>	
	14 1070		
	/.W. CO.		
	WW. CO.	1	
$\sim$	CALL SOM	/	
18. I hereby certify that the foregoing	is true and correct	0	6 5 76
[aV., 6]	Cuque TITLE_	Superintendent	6-5-76 
SIGNED (ACTION	Title		
(This space for Federal or State of	office use)		