

7. Methods for Handling Waste Disposal

Waste Disposal: Well cuttings will be disposed in reserve pit. Barrel trash containers to be in accessible locations within drill site area during drilling and completion procedures. All detrimental waste will be hauled away, burned or buried with a minimum cover of 24" of dirt. See Exhibit "D" for location of pits. If well is productive, maintenance waste will be placed in special trash cans and hauled away periodically.

8. Ancillary Facilities

None

9. Well Site Layout

Exhibit "D" shows the relative location and dimensions of the well pad, mud pit, reserve pit, etc.

10. Plans for Restoration of Surface

Pits will be backfilled and leveled as soon as practical to original condition. Commencement of rehabilitation operations will immediately follow removal of drilling and completion equipment from location and rehabilitation of the surface is planned to be completed within 45 days from commencement. Surface will be leveled and properly conditioned as required by USGS after consulting with proper surface managing agency.

11. Other Information

A. Terrain: "A" through "C" refer to the attached archaeological report.

B. Soil:

C. Vegetation:

D. Surface Use: Suitable for grazing.

E. Ponds and Streams: None within one mile.

F. Water Wells: None within one mile.

G. Residences and Buildings: None within one mile.

H. Arroyos, Canyons, Etc: See attached topographic map, Exhibit "B".

I. Well Sign: Sign identifying and locating well will be maintained at drill site with the spudding of the well.

J. Open Pits: All pits containing mud or other liquids will be fenced.

K. Archaeological Resources: None observed.

RECEIVED

NOV 14 1978

U. S. GEOLOGICAL SURVEY  
BUREAU OF GEOLOGY