

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Amoco Production Co.

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, N M 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

765' FSL x 1120' FEL

RECEIVED

4. PERMIT NO.

JAN 29 1986

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7484' GR

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla Apache A-118

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache Tribe

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A-118

Jicarilla Apache Tribal

9. WELL NO.

17

10. FIELD AND POOL, OR WILDCAT

Ojito Gallup-Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SE/SE Sec 26, T26N, R3W

12. COUNTY OR PARISH

13. STATE

Rio Arriba New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Squeeze to cover Ojo Alamo X

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

Amoco Production Company requests approval to squeeze the Ojo Alamo
of the above referenced well according to the attached procedure.
This is in response to your request on January 15, 1986. Reference
Jicarilla Contract 118 (WC) 3162.3-1(I) (016).

RECEIVED
FEB 24 1986
OIL CON. DIV.
DIST. 3

hereby certify that the foregoing is true and correct

SIGNED B. S. Shaw TITLE Adm. Supervisor

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED
DATE 1-20-86

FEB 20 1986
DATE 1-20-86
FOR M. MILLENBACH
AREA MANAGER

*See Instructions on Reverse Side

NMOCO

FARMINGTON DISTRICT
COMPLETION PROCEDURE

Date: 1/20/86

WELL NAME: JICARILLA APACHE A118 #17

FIELD OSITO GALLUP - DAKOTA

LOCATION: 765' FSL, 1120' FEL, SEC 26 T26N,
R3W, RIO ARIZONA COUNTY, NEW MEXICO

FORMATION(S) GALLUP

ELEVATIONS: KB: 7491' TD: 8525' PBD: 8483'

CASING: 8 5/8" 24# K-SS CSA 450'
5 1/2" 17# K-SS CSA 13-73' AND 6736'-8525'
5 1/2" 15.5# K-SS CSA 73' - 6736'

LOGS: DIL-GR-SP; SOL-DSN-GR-CAL

DV TOOL SET AT: 5104'

PURPOSE: SQUEEZE TO COVER OLD ALAMO

DBB
BJW

TWE

GOM

MCH
RGH
BVD
GMK


RWO/AJM

2DF

EDA
ENGR

FILE

WELLBORE SKETCH



PROCEDURE

- ① SET CAST IRON BRIDGE PLUG AT 3780'.
- ② PERFORATE 3780' AT 4 JSPP.
- ③ ESTABLISH CIRCULATION THROUGH BRADENHEAD.
- ④ SET CMT RETAINER AT 3730'.
- ⑤ SQUEEZE WITH 100 SX CLASS B CEMENT CONTAINING 0.6% FLUID LOSS ADDITIVE.
- ⑥ RUN TEMPERATURE SURVEY TO DETERMINE CEMENT TOP.

DISTRICT MANAGER

R. J. Bourssard

DISTRICT ENGINEER

[Signature]

DISTRICT DRILLING SUPERVISOR

T. W. Egan

ENGINEER ED ALIZADEH X DANA DELVENTHAL

DATE 1/20/86