UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	The state of the second	
Sundry Not	tices and Reports on Wel	ls
1. Type of Well GAS	DECEIVED MAR 3 1 1994 OIL CON. DIV.	5. Lease Number Jic.Contract 98 6. If Indian, All. or Tribe Name Jicarilla Apache 7. Unit Agreement Name
2. Name of Operator MERIDIAN OLL 3. Address & Phone No. of Opera PO Box 4289, Farmington, NM 4. Location of Well, Footage, S 1165'FNL, 1450'FEL Sec.18, S	1 87499 (505) 326-9700 Sec., T, R, M	8. Well Name & Number Jicarilla 98 #11 9. API Well No. 30-039-25307 10. Field and Pool Tapacitos PC/ Blanco MV
12. CHECK APPROPRIATE BOX TO IN Type of Submission Notice of Intent _x_ Subsequent Report Final Abandonment	Type of Ac Abandonment _x Recompletion _ Plugging Back	
	that cement for 4 1/2" casing was not nt with completion rig. Per the CET-Cl f cement is at 3200', with top of the Oje	BL-GR Cement Advisor log attached, it
	Title Regulatory Af	<u>fairs</u> Date 2/8/94
(This space for Federal or State APPROVED BY SHIRLEY MONDY CONDITION OF APPROVAL, if any:	Title Lands and Mine	MAR 3 0 1994