6 MMS Emn

1 Navaio Nation

Dec. 1973	r - mpproveu.
UNITED STATES	Budget Bureau No. 42-R1424  5. LEASE
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	NOO-C-14-20-4155A  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGIOAL JUNYLI	1
CUMPRY NOTICES AND DEPORTS ON WELLS	Navajo 7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	1
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1 21	AOK
1. oil gas other	9. WELL NO.
2. NAME OF OPERATOR	1
DUGAN PRODUCTION CORP.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Wildcat Sm Wolfmin
P 0 Box 208, Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
halour)	Sec. 33 T25N R19W
AT SURFACE: 660' FNL - 660' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
PEGLIFOT FOR ARROUND TO	6448' KB, 6437' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	
FRACTURE TREAT RECEIVI	ED
REPAIR WELL TO TO	(NOTS: Note:
PULL OR ALTER CASING OCT 25 198	(NOTE: Report results of multiple completion or zone hange on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	
ABANDON* U. S. GEOLOGICAL SI FARMINGTON, N.	JRVEY
(other)	M
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent. This well was plugged and abandoned 10-16-82 in	rectionally drilled, give subsurface locations and to this work.)*  the following manner:
1. Spotted 30 sk cement plug 6570-6305'.	
2. Spotted 25 sk cement plug 5875-5655'.	
<ol> <li>Spotted 30 sk cement plug 6570-6305'.</li> <li>Spotted 25 sk cement plug 5875-5655'.</li> <li>Spotted 25 sk cement plug 3920-3700'.</li> <li>Spotted 25 sk cement plug 3210-1990'.</li> <li>Shot off 5½" casing at 1091'.</li> <li>Spotted 25 sk cement plug 1090-1000' i</li> </ol>	JAN,
4. Spotted 25 sk cement plug 3920-3700 .	O/ 2 71985 1
5. Shot off $5\frac{1}{2}$ " casing at 1091'.	
6. Spotted 25 sk cement plug 1090-1000' i	nside 8-5/8" casing Diray Diray
7. Spotted 25 sk cement plug 170-80'.	is the 0-0/0 castily.
·	·n+
8. Installed dry hole marker w/ 5 sx ceme	:IIL.
Location will be cleaned and restored and wills time.	ubmit sundry for rehabilitation at th
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct  SIGNED TITLE Geologist  (This space for Federal or State office  APPROVED BY TITLE	NED
Canlories	10 22 ROPROVICED
SIGNED IN LIMIT JACOBS TITLE GEOLOGIST	DATE 10-22-DAT MENUEL
(This course for Federal or Share W	AS AIVI
(This space for Federal or State office APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	~ 1 9 1984
APPROVED BY	DEC 13 TO WEE
CONDITIONS OF APPROVAC, IF ANT:	

Approved as to plugging of the well bore.

Liability under bond is retained until uctions on Reverse Side

M. MILLENBACH WAREA MANAGER