
Form 9-831 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe,	N.M.
Lease No.	SF 078064	
[]mit	Carson	

SUNDRY NOTICES AND REPORTS ON WELLS

	1 11		. <u> </u>
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE	PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WA	1 1	SUBSEQUENT REPORT OF ALTERI	
NOTICE OF INTENTION TO RE-DRILL	OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRI	LLING OR REPAIR
NOTICE OF INTENTION TO SHOOT O	R ACIDIZE	SUBSEQUENT REPORT OF ABAND	ONMENT
NOTICE OF INTENTION TO PULL OR	ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON	to Injector X		
(INDIC	ATE ABOVE BY CHECK MARK NATUR	E OF REPORT, NOTICE, OR OTHER	R DATA)
Co rson Unit Well No. 23–24 is loca		line and 1980 ft fr	om W line of sec. 24
	25% 12%	NeMePelle	W me or see
NE 52 24			
(1/4 Sec. and Sec. No.)	(Twp.) (Range) San Jua	•	New Mexico
Bisti (Field)	(County or Subdi		(State or Territory)
auts:			
sposed Works		. 15	
Prossure test tubir		. To win.	
Pull tubing and bai	.l clean.	ud such while m	unning aloan Doint Look-
2-3/8" open-enc	led tubing to bottom	and swap while r	unning clean Point Look-
	with Iriton X-100 c	letergent) down cas	sing. When fluid cleans
up, pull tubing.	• • • • • • • • • • • • • • • • • • •	h nomfometic	~~
Fun 2-3/8" tubing v	with packer ten feet	, above perioration	us. oo uninhihited fluid. Set
throp 60 obls. Of in	inibited water down	annutus to dispra	ce uninhibited fluid. Set
gacker and fill wit	in inhibited water.		A Commence of the Commence of
	emperature surveys a		re operation of many be commenced
I understand that this plan of wo		2 - 2	DEC 25 19E.
Company Shell Gil Co	Epany		28 -
<u>-</u>			[Gi/] 1951]
Address P. C. Box 12	r i	Original Sig	ned By

Faraington.	*************************************	W. M. MAS	SHALL STORY
		W. M. MA3	***
	N.JA.		
		W. M. MAS By W. B. Max	