

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(OTHER INSTRUCTIONS ON REVERSE SIDE)

Form approved
Revised Edition No. 42 R1124
3. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for completion of a well or to design or plug back to a different reservoir.
See APPLICATION FOR PERMIT for each purpose also.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR		7. UNIT AGREEMENT NAME	
Skelly Oil Company		East Bisti Unit	
3. ADDRESS OF OPERATOR		8. FARM OR LEASE NAME	
1860 Lincoln Street - Denver, Colorado 80203		9. WELL NO.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		10. FIELD AND FOOT, OR WILDCAT	
1980' FSL and 1980' FEL Section 23-25N-11W		Bisti Lower Gallup	
11. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
15. ELEVATIONS (Show whether OF, RT, GR, etc.)		12. COUNTY OR PARISH	
6559' KB		San Juan	
		13. STATE	
		New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETION ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

All depths shown are from Ground Level.

9/14/71 - MI&RU Aztec Well Service Unit. Pulled rods.
Spotted cement plug from 5112' to 5012'. Pulled and laid down 2" tubing.
Worked 5 1/2" casing to free same. Rigged up Blue Jet, shot casing off at 1456'.
Spotted cement plug from 1506' to 1300', 50' below casing stub and 156' above casing stub. Pulled casing to 660'. Spotted cement plug from 660' to 560'.
Pulled total 43 joints 1464' of 5 1/2" casing.
Spotted 10' cement plug in surface casing. Installed dry hole marker.
Completed P&A 9/14/71.



18. I hereby certify that the foregoing is true and correct

SIGNED Lo L. Biele TITLE Lead Clerk DATE December 15, 1971.

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: