Form 2, 323

## UNITED STATES

Form approved. SUBMIT IN TRIPLICATE.

DEPAR	TMENT OF THE INTER GEOLOGICAL SURVEY	SF 078067		
SUNDRY NO	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
OIL X GAS WELL OTHER  2. NAME OF OPERATOR  Shell Oil Company	7. UNIT AGREEMENT NAME  Carson Unit 8. FAEM OR LEASE NAME  9. WELL NO. 43-14  10. FIELD AND POOL, OR WILDCAT  Bisti 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 14-T25N-R12W			
3. ADDRESS OF OPERATOR 1700 Broadway, Denver				
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  1980 FSL & 660 FEL Section 14				
14. PERMIT NO.	15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	12. COUNTY OB PARISH 13. STATE  San Juan N. Mexico	
16. Check	Appropriate Box To Indicate Nation to:		Other Data DUENT REPORT OF:	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other) (Note: Report result Completion or Recom	REATMENT ALTERING CASING	
17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is directed nent to this work.) •	OPERATIONS (Clearly state all pertine) ectionally drilled, give subsurface local subsurface	ations and measured and true verti	s, including estimated date of starting any cal depths for all markers and zones perti-	



WILL SEND FINAL SUNDRY WHEN LOCATION CLEANED AND READY FOR INSPECTION

KECEIVED

AUG 1 1977

U. S. GEOLOGICAL SURVEY

18. I hereby certify that the loregoing is true and corr	Div. Opers. Engr.	DATE <b>JUL</b> 2 9 1977
(This space for Fee Anl o 1) Cee 1) ED  APPROVED B CONDITIONS OF APPROVED 17 ANY 1002	TITLE	DATE
cc: New Mexico OSCC Waterhmen  For JAMES F. SIMS  DISTRICT ENGINEER	*See Instructions on Reverse Side	

PLUG AND ABANDON WELL				BISTI
SHELL OIL COMPANY	LEASE	CARSON UNIT	WELL NO.	43-14
	DIVISION _	WESTERN	ELEV	
FROM: 6/7-8/77	COUNTY	SAN JUAN	STATE	NEW MEXICO

NEW MEXICO
BISTI FIELD
Carson Unit 43-14
(P&A)

"FR" TD 5025. WO #528926 provides funds to plug and abandon well. 6/6 RU Bedford; unable to release Bkr tbg AC @ 4950. Loaded hole w/mud. Spt'd 25 sx cmt mixed w/1# flocele/sx. Displ'd cmt out of tbg to 4600' w/18 BW. Backed off tbg @ 1603. Pulled & LD tbg.

JUN 07 1977

Carson Unit 43-14 (P&A)

TD 5025. RU hyd jacks; did not find enough free pipe. Perf'd Fruitland Coal & Pictured Cliffs interval 1220-21 w/4 jets/ft. Spt'd 50 sx cmt plug. Closed Bradenhead & displ'd 20 sx thru perfs @ 1220-1221. Max press 650 psi; final press 450 psi. WOC 2 hrs; 0 press. Shot off csg @ 720' & spt'd 35 sx cmt plug @ csg stub. Pulled csg to base of Ojo Alamo 400' & spt'd 35 sx cmt plug. Pulled csg to base of 8-5/8 csg & spt'd 25 sx cmt plug. Fin'd pull'g csg. Installed abandonment marker w/10 sx cmt plug. RD Bedford Inc. 6/7/77.
FINAL REPORT