

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir,
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
14-20-60-325

6. If Indian, Allottee or Tribe Name

7. If Unit or CA. Agreement Designation

Central Bisti Unit

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Central Resources, Inc.

3. Address and Telephone No.

P.O. Box 1247, Bloomfield, New Mexico 87413 (505)-692-3476

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL, 660' FEL, Sec 8, T25N, R12W

8. Well Name and No.
29

9. API Well No.

30-045-05476

10. Field and Pool, or Exploratory Area
Bisti Lower Gallup

11. County or Parish, State

San Juan County, New Mexico

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Central Resources, Inc. intends to plug the well in accordance with regulations. Production equipment will be removed and the well will be plugged as specified. **Perforate and squeeze will be used unless casing can be recovered over the specified interval or there is evidence cement is in place behind the casing.**

Proposed procedure:

- Notify the Farmington BLM office at 505-599-8907 24 hours prior to commencement of plugging operations.
- Pull all retrievable downhole production equipment.
- Set a CIBP at 4700' and spot 50' of cement on top.
- Set a 100' cement plug from 1833 to 1933' across Menefee top at 1883'.
- Set a 100' cement plug from 999' to 1099' across the Pictured Cliffs at 1049'.
- Set a 100' cement plug from 589' to 689' across the Fruitland Coal at 639'.
- Set a 100' cement plug from 280' to 380' across the surface casing shoe at 330'.
- Set a 50' cement plug from surface to 50'.
- Cut wellhead and install dry hole marker. Clear and remediate location.

Please take into account the number of existing P&A procedures, the number of P&A procedures you have requested and the available equipment and allow Central Resources, Inc. until the end of 2000 to complete this abandonment.

14. I hereby certify that the foregoing is true and correct

Signed Rodney L. Seale
Rodney L. Seale

Title District Manager

Date April 24, 2000

(This space for Federal or State office use)

Approved by _____

Title _____

Date 5/22/00

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

*See Instruction on Reverse Side

CENTRAL RESOURCES, INC.

Central Bisti Unit No. 29

Review Date:

4-17-00 by Rod Seale

Elevation: 6216' GL, 6223' KB

Location: 1980' FSL, 660' FEL, Sec 8, 25-N, 12-W, San Juan County, New Mexico

Field: Bisti Lower Gallup

Zone: Lower Gallup

Perfs: 4763' - 4859'

Spud Date: August 24, 1959 12:00 AM

8 5/8" 24# J55 ST&C CSA 330' w/ 225sx

TOC @ 3300' by Temp Survey

Tubing was pulled on 2-80

Perf over 4763-70, 4772-82, 4792-4802, 4808-15, 4819-25, 4833-44 & 4848-59

PBTD: 4920'

4 1/2" 9.5# J55 CSA 4952' w/ 350 sx

TD: 4956'