

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa Fe
Lease No. 080375
Unit Sheets

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Subsequent Report of Sand-Oil</u>	
	<u>Treatment</u>	<u>x</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 25th, 19 56

Well No. 5 is located 1340 ft. from N line and 395 ft. from E line of sec. 12

SE/4 NE/4 Sec 12 25N 3W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Ballard San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6904 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-14-56 Cleaned out to TD 2702'. Gas too small to measure. Sand-oil treated 2730' to 2782' with 6,220 gallons diesel oil and 20,000# sand, flushed with 2,800 gallons diesel oil. Maximum treating pressure 1200#, injection rate 36 BPM. Set Baker 2B CI bridging plug at 2720'. Perforated 2691½ to 2703' with 4 holes per foot. Sand-oil treated through perforations with 8,527 gallons diesel oil and 20,000# sand, flushed with 2,700 gallons diesel oil. Maximum treating pressure 1500#, injection rate 26 BPM. After treatment flowing 1,466 MCF/day.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON-MONTIN
 Address 405½ West Broadway
Farmington, New Mexico

By [Signature]
 Title Field Superintendent



