(SUBM	Form 9-331 b (April 1952)			
Un				
DEPARTME				
CEO				1

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Bu Ap	dget Bureau No. 42–R359.4. proval expires 12–31–60.
Indian Ag	ney Havajo
Allottee	Hoeks-Da-Not
	14-20-603-1292

	GEOL	OGICAL SUR	VEY	Lease No.	-003-127
SUNDRY	NOTICES .	AND REF	PORTS ON	WELLS	
NOTICE OF INTENTION TO DRILL		SUBSEQUEN	T REPORT OF WATER	SHUT-OFF	I
NOTICE OF INTENTION TO CHANGE P	LANS	SUBSEQUEN	T REPORT OF SHOOTI	NG OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATE	ER SHUT-OFF	SUBSEQUEN	T REPORT OF ALTERI	NG CASING	
NOTICE OF INTENTION TO REDRILL	OR REPAIR WELL	SUBSEQUEN	T REPORT OF REDRIL	LING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR	ACIDIZE	SUBSEQUEN	T REPORT OF ABANDO	NMENT	
NOTICE OF INTENTION TO PULL OR A NOTICE OF INTENTION TO ABANDON		SUPPLEMEN	TARY WELL HISTORY		
(INDICAT	E ABOVE BY CHECK MAR	_		DATA)	
Benally		Derver	Colorado (Minder A	, 19.59.
Well No is loc	ated 1960 ft. f	from $\{S\}$ line a	nd 1980 ft. fr	om $\{W\}$ line of s	ec 5
5M/A 8ee. 5	2策	124	MAPPA		
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
Bisti - Gallup	See Jeen	County		MaxLeo	
(Field)	(Coun	ity or Subdivision)		(State or Territory)	
The elevation of the derrick	floor above sea!	level is	ft.		
	DETA	AILS OF WO	RK		
State names of and expected depths to	objective sands; show	sizes, weights, and le	ongths of proposed cas	ngs; indicate mudding	g jobs, cement
		J-55 STAC 1k coment.	R-2 casing, Pumped plug	set at 4921'	RKB.
				COM.	
I understand that this plan of work	must receive approval	in writing by the G	DIST	e G orati no may be co	ommenced.
Company PHILLIPS P	ETROLIZE COMP	<u> </u>		<i></i>	~
Address 1200 Benyer Cl	ab Building		7		_

Company PHILLIPS PETROLEUM COMPANY

Address 1200 Denver Club Building

By /// / Title Division Superintendent



de la companya de la