

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

LOCATE WELL CORRECTLY

[illegible]

The summary on this page is for the condition of the well at above date.

Date _____ Title _____

No. 8 from
to
with no drop in pressure. Drilling operations were resumed.
No. 4 from
to
on March 12, 1957, 9-5/8 casing was set at 1510'. At 1000 feet casing
waiting on cement for 24 hours. Casing and water sands
pounds pressure for 30 minutes with no drop in pressure. Drilling
No. 6 from
to

RECEIVED
MAR 13 1957
COMM. DIV.

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and the results. If there were any changes made in the casing, state fully, and if any casing was "sidetracked" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

HISTORY OF OIL OR GAS WELL

[illegible]