Submit to Appropriate District Office State Lease - 4 copies Fee Lease - 3 copies

Energy, Minerals and Natural Resources Department

Form C-102 Revised 1-1-89

OIL CONSERVATION DIVISION DISTRICT 1
P.O. Bux 1980, Hobbs, NM 88240

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 Hold c-104 for MC +NSL

DISTRICT II P.O. Drawer DD, Artesia, NM \$1210

DISTRICT III 1000 Rio Brazos Rd., Azisc, NM #7410 WELL LOCATION AND ACREAGE DEDICATION PLAT All Distances must be from the outer boundaries of the section

Operator	· ····	<del></del>	Losse				Wall No.	·
Giant Exploration & Production Company			Carson Unit 19			41-49 Extsting		
Jan Latter Section	os Townshi	P	Range		4	County		
Α	19	25 North	11	West	NMPI	yı s	an Juan	
Actual Footage Location of	Well:							ľ
	rom the North	line and	614	<u> </u>	feet from	m the E	ast line	
Ground level Elev.	Producing Formation		Pool				Dedicated Acreage:	
4/10 6409 Est. Fruitland		Basin Fruitland Coal			320 Acres			
1. Outline the acreage dedicated to the subject wall by colored pencil or hachure marks on the plat below.								
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).								
3. If more than one lease of different ownership is dedicated to the well, have the interest of all owners been consolidated by communitization,								
unitization, force-pooling, etc.?								
Yes No If answer is "yes" type of consolidation  If answer is "no" list the owners and tract descriptions which have actually been consolidated. (Use reverse side of								
this form if poccessary.								
No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, aliminating such interest, has been approved by the Division.								
or until a non-sta	indard unit, eliminating su	ch interest, has been ap	proved by the Di	IVIAIOA.	<del></del>		<del></del>	
ļ ļiiiiiii						OPERATOR CERTIFICATION		
	-	E		i 1 657'			certify that the i	
	; 	E	i	1			un in irus and comp whedge and belief.	10 IA2
1	1	E		<b>O</b> 61	∡∃ I		,	
	i 1	E		i oʻ	"∃∣	Signature		1
	 	E		i I	=	41	C' Culi	T
	1	E			$\exists$ /	Printed Name		
		. — - [		<u></u>	•===	John C. Cor	bett	
	1 ,	E		i I	=	Position .		
	i i			i I	= 1		ice President	
	i I	F -		i !	П	Company		
	1	E		] }	Ξ'	Giant Explo	oration & Produ	ction Co
	1	F		] 	$\equiv$	October 9,	1001	
	 	E		! !	Ξ'			
O. E.C.	5 19At	ion = 19		SF-078063	_===	SURVE	YOR CERTIFICA	NOIL
U) E O		- E		! !	∄	1 hereby certi	ify that the well loca	ition shown
IN	11001	E		1	≡	on this plat	was plotted from fu	ld moves of
OCTI	, <b>5</b> 199 <b>1</b> .	F		1	=		is made by me or	under my s true and
011 00	ON. DIV.	E			Ξ	supervison, a		
OIL C	JIM. LIVI	E		1	$\exists$	belief.		-
DI	s†. 3	E		1	∄		4.	
	ļ	E		1	目	Date Surveye	October 4, 19	
				1 4		Cionatura A C	Seal of	
		E		i i	∄	Professional	Surveyor FISCAL	£.
	,	E		1	$\equiv$	37	×	State of the state
	l I	E		1	$\exists$	36	Salar Salar	荒夏
	ļ	E		1	3		2000	70 %
	1	E		1	3	E daze	L'Hice Por	صري ر
	l i	<b>H</b>	11111111111	<b>  </b>	шП	Conficete No		,
						Edgar"L.	Risenhoover, :F	. s
0 330 660 990	1320 1650 1900 2	310 2640 2	000 1500	1000 500	•	1.6	Walter Charles	

