Form 3160-5	1	FORM APPROVED		
(June 1990)		Budget Bureau No. 1004-0135		
(Julie 1990)	RECEIVED	Expires: March 31, 1993		
UNITE	D STATES SIM MAIL ROOM	5. Lease Designation and Serial No.		
DEPARTMENT	OF THE INTERIOR	SF 078063		
BUREAU OF LA	ND MANAGEMENT 55 SFP 11 PM 2: 11	6. If Indian, Allottee of Tribe Name		
SUNDRY NOTICES A	ND REPORTS ON WELLS			
Do not use this form for proposals to dril Use "APPLICATION FOI	or to deepen or reentry to a different reservoir, N	7. If Unit or CA. Agreement Designation		
SUBMIT IN TR	IPLICATE	Carson Unit		
1. Type of Well		8. Well Name and No.		
X Oil Well Gas Well	Other	Carson Unit #34-19		
2. Name of Operator	9. API Well No.			
Giant Exploration & Production Con	ipany	30-045-13272		
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area		
P.O. Box 2810, Farmington, New Me	exico 87499 (505)326-3325	Bisti Lower Gallup		
4. Location of Well (Footage, Sec., T., R., M., or	11. County or Parish, State			
660' FSL, 1980' FEL, Sec. 19, T25N,	R11W	San Juan, New Mexico		
12. CHECK APPROPRIATE BOX(s) TO INI	DICATE NATURE OF NOTICE, REPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION			
	Abandonment	Change of Plans		
X Notice of Intent	Recompletion	New Construction		
	Plugging Back	Non-Routine Fracturing		
Subsequent Report	Casing Repair	Water Shut-Off		
	Altering Casing	Conversion to Injection		
Final Abandonment Notice	X Other Return to Production	Dispose Water		
	`	te: Report results of multiple completion on Well		
		npletion or Recompletion Report and Log form.)		
	Tlearly state all pertinent dates, including estimated date o and measured and true vertical depths for all markers and			
uncetionally drined, give substituce locations	and measured and a de vertical depuis for an markers and	zones pertinent to ans work.		
	Company intends to return the subject well to pro	duction as follows:		
1) Clean out to a PBD of 4990'.				
2) Pressure test casing.		all partitions of the second		
3) Acidize existing perforations (4846'-54', 4885'-89', 4903'-13', 4927'-37', 4944'-	53') with 1000 gal. 15% HCl.		
4) Install production tubing string. (Note: if casing leaks are encountered, a 3-1/2" liner with isolating packers				
, ,	nterval prior to running the production string.)	-		
5) Install pumping unit.	5 1			
6) Return well to production.		WEWE SEE		
o) Return wen to production.		UU GED A SAFET W		
		JEF O load with		

ODL CORL DAY,
DISL 3

14. I hereby certify that the foregoing is true and correct			SEP 0 7 1995
Signed Paul K, Williams	Title Area Engineer	Date	-2EE / 1 1999
Paul R. Williams			
(This space for Federal or State office use)			
Approved by	Title	Date _	
Conditions of approval, if any:			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

*See Instruction on Reverse Side

