

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-21424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Carson Unit

8. FARM OR LEASE NAME

Unit

9. WELL NO.

200

10. FIELD AND POOL, OR WILDCAT

Bisti Field

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

1/4 SE 1/4 Section 13-
25N-R 12W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1. OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Heil Oil Company (Rocky Mountain Division Production)

3. ADDRESS OF OPERATOR

1700 Broadway, Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 175' P.L. and 1665' P.L. Sec 13

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6408 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

as per attached plugging prognosis

Please forward (2) approved copies to:

Oil and Gas Conservation Commission
1000 Rio Brazos Road
Albuquerque, New Mexico 87106

Attention Mr. W. C. Arnold, Supvr. & Oil & Gas Inspector

RECEIVED

NOV 8 1973

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

For: W. C. Arnold
Division Operations mgr.

TITLE

DATE 11-6-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

PLUGGING AND ABANDONING PROGNOSIS
CARSON UNIT 34X-13 (#200)
Sec. 13, T25N, R12W
BISTI FIELD, SAN JUAN COUNTY, NEW MEXICO

PERTINENT DATA:

Elev: 6408'
KB-GL: 11'
TD: 1330'
PBD: 1283'

Perfs: 1234'-1256'
Shell's W.I.: 100%
AFE: 588770

CURRENT STATUS: Shut in

PROCEDURE:


1. MI and R.U. pulling unit. Pick up a minimum of 1300-ft of available 2" tubing.
2. Check wellhead pressure and bleed off if any, then load well with 21 bbls of water (hole may not stand full).
3. R.U. cementers, and run in hole w/tubing open ended and set a bottom plug from approximately 1100' to TD w/ min. 20 sacks API class A cement w/2% CaCl₂.
4. Wait a min. of 3 hours before filling the hole w/water. Meanwhile pull tubing and remove wellhead.
5. Spot a top plug from 100' to surface w/10 sacks cement as above.
6. R.D. cementers and pulling unit.
7. Cut off casing 5' below the surface and weld on a casing cap and erect a permanent marker.


 SPC:psl

10/11/73

Div. O.E. K.R. Jordan

Div. P.E. F.A. Wise


B. L. Faulk



Carson Unit 34X-13 (#200)

8 $\frac{5}{8}$ " @ 326'

Calc. Cement top
@ $\approx$ 500 ft. Do
Not Attempt to
Recover Pipe.

Pictured Cliffs
Perfs 1234'-56'

4 $\frac{1}{2}$ " @ 1324'

PB 1283'

TD 1330'



10/16/73
SFC