Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

OMB No. 1004-0135 Expires July 31, 1996

	NOTICES AND REPORT	/a> NC)V 2001	NMSF -078062A
Do not use thi	s form for proposals to . Use Form 3160-3 (APD	for such proposals		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPL 1. Type of Well	ICATE – Other instri		HST. 3 ie side	7. If Unit or CA/Agreement, Name and/or No.
Oil Well X Gas Well Other				8. Well Name and No.
2. Name of Operator				Mudge 2 #300
Elm Ridge Resources, Inc.				9. API Well No.
3a. Address	3b. Phone No. (include	cra code)	30-045-21286	
PO Box 189 Farmington, NM 8	505-632-3476		10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R	., M., or Survey Description)			Basin Dakota
950' FNL & 1500' FEL				11. County or Parish, State
Sec. 8-T25N-R11W				San Juan, New Mexico
12. CHECK APPROPRIATE BOX(E	S) TO INDICATE NATURE	OF NOTICE, REPORT	, OR OTHER DA	TA
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (S	Start/Resume) Water Shut-Off Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Time About annual Valida	Change Plans	Plug and Abandon	Temporarily	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos	
Following completion of the involved ope	or recomplete horizontally, give will be performed or provide the rations. If the operation results in adomment Notices shall be filed	subsurface locations and mea: Bond No. on file with BLM n a multiple completion or re	sured and true vertica I/BIA. Required subsecompletion in a new	ossed work and approximate duration thereof, all depths of all pertinent markers and zones, sequent reports shall be filed within 30 days interval, a Porm 3160-4 shall be filed once have been completed, and the operator has

Elm Ridge ResourcesInc. plugged and abandoned the Mudge 300 #2 on October 4, 2001 as follows: MIRU Triple P Rig #6. Pulled to 35,000 80% of 1-1/2 tubing - parted tubing @ 2606'. TOOH w/1-1/2 tubing. TIH w/2-3/8" tubing and fishing tools. Tagged fish to work pipe. Fish over pipe, working the pipe and cleaning hole. Trip wash over pipe out to p/u cutters. Cut tubing, POOH with cut tubing. TIH and tag @ 4214' w/wireline. Pump cement @ 2-1/2 bpm @ 800 PSI. Reverse cement. TOOH w/overshot. TIH w/scrapper. TOOH w/scrapper and perf. @ 2085'. TIH w/retainer @ 2016'. TOOH w/retainer to 1240'. Laydown 25-joints. Establish circluation - test tubing to 1500 PSI - held. Set retainer. Pump 50 sx cement @ 1-1/2 bpm @ 800 PSI. RIH w/perf. @ 1290'. TIH w/retainer to 1240'. TIH w/perf @ 1026'. TIH w/retainer @ 976. Pump 50 sx cement. TIH w/perf. @ 568'. Pump cement and circulate to surface. Plugging complete.

Certified Return Receipt # 7001 0320 0001 0934 5711

	·			
14. I hereby certify that the foregoing is true and correct				
Name (Printed/Typed)	Title			
Trudy Grubelnik		Production Technician		
Signature Medi Muha M	Date	October 25, 2001		
THIS SPAC	E FOR FEDERAL OR STATE U	iE.		
Approved by	Title	Date		
Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the standard would entitle the applicant to conduct operations thereon.	ot warrant or Office subject lease	10 j		
Title 18 II C C Section 1001 makes it a crime for any namen knowingly and	J: 11G-11-141-4 J4	Cut. XX 1. Lo.		

ime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.