Form	9-331	
(Mav	1963)

FRACTURE TREAT

REPAIR WELL

(Other)

SHOOT OR ACIDIZE

UNITED STATES DEPARTMENT OF THE INTERIOR SUBMIT IN TRIPLICATE* (Other instructions on reverse side)

SHOOTING OR ACIDIZING

Form approved. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

ABANDONMENT*

SF 080373
6. IF INDIAN, ALLOTTEE OR TRIBE NAME GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL 8. FARM OR LEASE NAME 2. NAME OF OPERATOR Hanson Tenneco Oil Company 9. WELL NO. Suite 1200 Lincoln Tower Bldg., Denver, Colorado

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 3. ADDRESS OF OPERATOR 80203 10. FIELD AND POOL, OR WILDCAT Basin Dakota
11. SEC., T., E., M., OR REK. AND
SURVEY OR AREA 950' FNL and 1800' FEL T25N Sec. 6. T25N. RIOW 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 6542.0' GR San Juan New Mexico Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF : NOTICE OF INTENTION TO: REPAIRING WELL WATER SHUT-OFF TEST WATER SHUT-OFF PULL OR ALTER CASING ALTERING CASING FRACTURE TREATMENT

(Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Spudded 12-1/4" surface hole 9/12/73. Drilled to 615' KDB. Ran 19 its. 8-5/8" 24# K-55 w/GS and insert float and set at 615'. Cemented with 400 sacks class "A" with 2% CaChl, 1/8 by 1# Flo-cele. Circulated to surface. Plug down at 1:45 pm. 9/13/73. WOC 12 hours and tested casing to 1000 psi, held OK. Preparing to drill out from under surface casing.

DIST

18. I hereby certify that the foregoing is true and co	orrect	
SIGNED W.Q.	TITLE Production Clerk	DATE 9/17/73
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE

