

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Jennifer A. Salisbury
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

December 14, 2000

John Roe Dugan Production Corp. PO Box 420 Farmington NM 87499

Re: Grigsby Fed #2, N 07-25N-10W API 30-045-21507

Dear John:

The Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before February 1, 2000.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

Charlie T Perrin

Deputy Oil & Gas Inspector

cperrin@state.nm.us

Charlie T. Lerrin

CTP/mk

CC: CTP

Well File