16.

UNITED STATES SUBMIT IN DEPARTMENT OF THE INTERIOR Verse side)

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bur-au No. 42-R142LEASE DESIGNATION AND SERIAL NO.

| | MENT OF THE INTERIOR verse side) EOLOGICAL SURVEY | NOO-C-14-20-5321 |
|--|--|--|
| (Lie not use this form for propos | CES AND REPORTS ON WELLS als to drill or to deepen or plug back to a different reservoir. TION FOR PERMIT—" for such proposals.) | Navajo T, ibe |
| OIL GAS WELL OTHER | | 7. UNIT AGREEMENT NAME |
| 2. NAME OF OPERATOR TEXACO, Inc. Prod. | Dept. West U.S. | S. FARM OR LEASE NAME Navajo Tribe "BT" |
| 3. ADDRESS OF OPERATOR P. O. BOX EE, COI | tez, CO. 81321 | 9. WELL NO. |
| 4. LOCATION OF WELL (Report location of See also space 17 below) At surface NE 4NE 4 Sec. 16 | early and in accordance with any State requirements.* | Wildcat (Yah-Teh-Hey 11. Sec., T., R., M., OB BLK. AND SURVEY OR ALLA |
| 660' from North li | ne and 660' from East line. | S16, T25N, R18W |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5682' KB or 5669' GR | 12. COUNTY OR PARISH 13. STATE San Juan New Mex. |

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | | |
|-------------------------|----------------------|-----------------------|---|---------------------------|
| f: | | | (| |
| TEST WATER SHUT-OFF | PULL OR ALTER CASING | | WATER SHUT-OFF | REPAIRING WELL |
| FRACTURE TREAT | MULTIPLE COMPLETE | | FRACTURE TREATMENT | ALTERING CASING |
| SHOOT OR ACIDIZE | ABANDON* | | SHOOTING OR ACIDIZING | ABANDON MENT* |
| REPAIR WELL | CHANGE PLANS | | (Other) | Itiple completion on Well |
| (Other) | | | (Note: Report results of mu Completion or Recompletion F | teport and Log form.) |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

12-9-77. MIRUSU. Run free point survey; cut 2-7/8" EUE tubing at 3958'. Set 40 sx. cement plug on perfs. 6812 - 40'.

Set 30 sx. cement plug on tubing stub. Run 7" free point. Cut 7" csg. at 2862'. Set 50 sx. cement plug, 2752 - 2898'. Set 100 sx. cement plug 2321 - 2612'. Set 9-5/8" retainer @ 1577'. Set 25 sx. cement plug 1313 - 1577'. Filled hole with mud. Set 70' cement plug @ surface. Cut off wellhead - set dry hole marker and cleaned location.

| 18. I hereby certify that the foregoing is true and correct SIGNED Chrin R. Manc | TITLE | Field Foreman DANE | 2-23-78 |
|--|--------------|--|---------|
| (This space for Federal or State office use) | | 8254 | |
| APPROVED BYCONDITIONS OF APPROVAL, IF ANY: | TITLE | DATE | |
| | | \(\lambda = \lambda \)\(\lambda = \lambda \) | |
| *Se | e Instructio | ons on Reverse Side | |

USGS(4) NMOCC(3) The Navajo Tribe-GLE-ARM-JHP