| 4-USGS 1-Fil | e | (|
|----------------------------------|--|--|
| Form 9-331 (May 1963) | UNITED STATES SUBMIT IN DEPARTMENT OF THE INTERIOR verse side) | TRIPLICATE* Form approved. Budget Bureau No. 42-R1424 5. LEASE DESIGNATION AND SERIAL NO. |
| | GEOLOGICAL SURVEY | NM 25443 |
| | NDRY NOTICES AND REPORTS ON WELLS is form for proposals to drill or to deepen or plug back to a different Use "APPLICATION FOR PERMIT—" for such proposals.) | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME reservoir. |
| OIL GAS WELL WELL | X OTHER | 7. UNIT AGREEMENT NAME |
| 2. NAME OF OPERATOR | ed Vinda | 8. FARM OR LEASE NAME |
| Dugan | Red Mac | |
| 3. ADDRESS OF OPERAT | | 9. WELL NO. |
| Box 23 | 4, Farmington, NM 87401 | |
| See also space 17 t | (Report location clearly and in accordance with any State requirements elow.) | .* 10. FIELD AND POOL, OR WILDCAT |
| At surface | 1450' FSL - 1600' FEL | Undesignated - PC |
| | | 11. SEC. T., B., M., OR BLK. AND SURVEY OR AREA |
| | | 3Sec 3, T25N, R12W |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6228 GR | CON THE TARISH 13. STATE |
| .6. | | San Juan NM |
| | Check Appropriate Box To Indicate Nature of Notice | |
| | TOTAL OF INTERNIOR TO | SUBSEQUENT REPORT OF: |
| TEST WATER SHUT | | T-OFF X REPAIRING WELL |
| FRACTURE TREAT | MULTIPLE COMPLETE FRACTURE T | |
| SHOOT OR ACIDIZE | ABANDON* SHOOTING O | \ |
| REPAIR WELL | CHANGE PLANS (Other) (NOTE | Completion X: Report results of multiple completion on Well |
| (Other) | ·——· ' Combi | etion of Recompletion Report and Log form) |
| proposed work. nent to this work | OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give If well is directionally drilled, give subsurface locations and measured)* | pertinent dates, including estimated date of starting and and true vertical depths for all markers and zones perti |
| | | |
| 9-14-75 | | • |
| | and one cut off shoe jt of 2-7/8" OD 6.5# | |
| | GR, cemented $w/75$ sx Halliburton lite $w/\frac{1}{2}$ | |
| | ng wtr ahead and mixing cement, had circ i | |
| | t, pipe stuck while reciprocating and woul | d not go back to ground level, |
| POB 11:45 A | M, 9-13-75. | |
| 9-15-75 | | |
| | e down to approx 800', Go International ra | r Gamma-Ray Correlation Log |
| |), perf w/one 2-1/8" glass jet/ft 1134-40" | |
| | as or fluid entry), perf w/one 2-1/8" glas | |
| | 00 MCFGPD. Job complete 2:30 PM, 9-14-75. | |
| | <u>-</u> | I was the first of the |
| | | The face beautiful to the second second |
| | | 6.4075 |
| | | SEP 1 8 1975 |
| | | the common process are all |
| | | We will bring the by |
| | | |
| 8. I hereby certify the | t the foregoing is true and correct | |
| STONED IN | L Lesh Geologist | 9-16-75 |

9-16-75

TITLE .

Jim L. Jacobs
(This space for Federal or State office use)

APPROVED BY _____CONDITIONS OF APPROVAL, IF ANY: