Form 3160-5					FOD	M APPROVED	
(June 1990)						Budget Bureau No. 1004-0135	
.0			/		Expires: Mai		
	UNITED STATES					5. Lease Designation and Serial No.	
DEPARTMENT OF THE INTERIOR						14-20-603-1449	
BUREAU OF LAND MANAGEMENT					6. If Indian, Allot	tee or Tribe Name	
SUNDRY NOTICES AND REPORTS ON WELLS					Navajo		
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir,  Use "APPLICATION FOR PERMIT" for such proposals					7. If Unit or CA.	Agreement Designation	
Us				als			
	SUBMIT IN TRII	LICA	<u>re</u>				
1. Type of Well Oil Well X Gas Well Other					8. Well Name and		
2. Name of Operator					Ka Gee Ta	in #1	
•					9. API Well No.	500	
Central Resources, Inc.					30-045-22		
3. Address and Telephone No.						ol, or Exploratory Area	
P.O. Box 2810, Farmington, New Mexico 87499 (505) 326-3325  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					WAW Fru		
• • •					11. County or Par	•	
1550' FNL, 1850' FWL, Section 10, T25N, R12W						New Mexico	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION TYPE OF ACTION							
TILOFSOD	WIISSION	X	Abandonment	TIPEOFACI	Change of Plans		
X Notice of In	tent	H	Recompletion		New Construction	n	
A routee of m	tont .	H	Plugging Back		Non-Routine Frac		
Subsequent	Report	$\vdash$	Casing Repair		Water Shut-Off	cturing	
	Report	H	Altering Casing		Conversion to Inj	action	
Final Ahand	Ionment Notice	$\forall$	Other Revise	d	<u> </u>	ection	
Final Abandonment Notice				Dispose Water Note: Report results of multiple completion on Well			
						tion Report and Log form.)	
13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is							
directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*							
			,				
See attached procedure for proposed plugging operation.							
						ت <u>ک</u>	
				이들() 등		-	
	BORWEN.		CAMP A REAL		3 11 0 - 101		
(a)	ECEIVED			UU OCT 2	1 1998		
In(	- 10)						
ព្រ	OCT 2 1 1998			- @NL C@	N. DIV.		
_	TOOM DOWN				K. 3	A B	
(0)	IL CON. DIV	)		2700		<u> </u>	
_	DIST. 3						
~ <i>,</i>	manufacture of the same	تخسيسيد					
14 I hereby certify t	hat the foregoing is true and	correct					
Signed (Signed	nat Ale to legonights true and		District Mana	ger	Date 10/14/98		
Thomas DeLong  The District Wariager  Date 10/14/76							
		<del></del>					
Approved by	Federal or State (ffice use) Duane W. Spencer	Title			Date	town frankli	
Approved by		_ ''''					

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

Conditions of approval, if any:

## Plugging and Abandonment Procedure Ka Gee Tah #1 Attachment "A"

## **WELL DATA:**

Location:

1550' FSL, 1850' FWL, Section 10, T25N, R12W

San Juan County, New Mexico

TD:

1247'

PBTD:

1189'

Surface Casing:

5 1/2", 15.5 ppf, J-55 set @ 65'. Cement w/ 10 sks cement.

The State State of the Control

Production Casing: 2 7/8", 6.5 ppf, J-55, set @ 1242'. Cement with 75 sks cement.

Perforations:

1116-22', 1124-28' 2 JSPF

## PROCEDURE:

1. Pull and lay down 1 1/4" tubing.

2. Mix and pump 27 sacks (31.9 cuft) cement down casing. Displace with water to 350'. Shut down and wait on cement.

A Salar

- 3. Rig up wireline services and tag cement. Perforate squeeze holes at 140'.
- 4. Establish circulation down casing, through perforations at 140', up annulus and out bradenhead.
- 5. Mix and pump 20 sacks (23.6 cuft) cement down casing through perforations, up annulus and out bradenhead. Leave casing and annulus full of cement.
- 6. Cut off casing and install regulation dry hole marker. Reclaim location per BLM regulations.

the south describing the second

The second of the second