

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir,
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
Giant Exploration & Production Company

3. Address and Telephone No.
P.O. Box 2810, Farmington, New Mexico 87499 (505)326-3325

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
860' FNL, 330'FWL, Sec. 22, T25N, R12W

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Giant Exploration & Production Company plans to Plug and Abandon the subject well as outlined in Attachment "A".

RECEIVED
MAR 28 1996
OIL CON. DIV.
DIST. 3

RECEIVED
MAR 28 1996
OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed Gregory E. McIntosh Title Senior Area Engineer

Date MAR 14 1996

(This space for Federal or State office use)

Approved by _____ Title _____ Date _____
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

*See Instruction on Reverse Side

APPROVED

for Shane on Spec

NMOCD

Giant Exploration & Production Company
Hunter Wash Well No. 2
860' FNL, 330' FWL, Section 22, T25N, R12W
San Juan County, New Mexico
Lease No. NMNM 25449

Attachment "A"

- Move in and rig up well service unit
- Set cement retainer at 4566'. Pump 29 sack (34.2 cuft) cement plug below retainer from 4566' to 4810' plus 50% excess to cover the perforations, top of the Lower Gallup formation and top of the Upper Gallup formation. Set 5 sack (5.9 cuft) cement plug on top of cement retainer.
- Perforate squeeze holes at 1480'. Set cement retainer at 1430'. Set 425 sack (501.5 cuft) cement plug inside (85 sack, 100.3 cuft) and outside (340 sack, 401.2 cuft) casing from 1343' to 550' to cover top of Mesa Verde formation, top of Pictured Cliffs formation and top of Fruitland formation.
- Perforate squeeze holes at 276'. Fill casing and casing annulus with 80 sack (94.4 cuft) cement plug.
- Cut off casing and install regulation dry hole marker. Clean and rehabilitate location.

Note: All cement plugs will be Class B cement mixed at 15.6 ppg, yield 1.18 cuft/sk.
8.33 ppg plugging fluid will be used between cement plugs.