

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
COMPLY WITH INSTRUCTIONS ON REVERSE
OF THIS FORMDATE RECEIVED
DEPT. OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SI-073050

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. WELL TYPE OIL ☐ GAS ☒ WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Hixon Development Company	8. FARM OR LEASE NAME Federal "C"
3. ADDRESS OF OPERATOR P.O. Box 2810, Farmington, New Mexico 87401	9. WELL NO. 9
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1750' FNL, 1850' FWL, Section 5, T25N, R12W	10. FIELD AND POOL, OR WILDCAT WAW-Fruitland-PC
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 5, T25N, R12W
15. ELEVATIONS (Show whether DF, RT, CR, etc.) GLE - 6159'	12. COUNTY OR PARISH San Juan
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD-1330', 7" 20# surface casing @ 94' with 80 sacks. Drilled 5" hole to 1330'. Well to be P & A as uncommercial WAW-Fruitland-PC stepout per telecon between A.L. Kuchera and Jim Simms (USGS) 10/25/79 as follows: Spot 250' (1250'-1000') 30 sack plug across PC-Fruitland coal; Spot 200' (800'-600') 25 sack plug across Fruitland-Kirtland; Spot 190' (10'-200') 30 sack plug across base of surface casing. Set regulation dryhole marker in 10 sacks cement.

Log tops as follows: Pictured Cliffs - 1109', Fruitland Coal - 1086', Fruitland Shale - 682', Kirtland - 108', Ojo Alamo - surface.

18. I hereby certify that the foregoing is true and correct

SIGNED

Petroroleum Engineer

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE 10-25-79

APPROVED
AS AMENDED

NOV 28 1979

JAMES F. SIMS
DISTRICT ENGINEER

*See Instructions on Reverse Side

NMOC