Form 9-331 (May 1963)

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other instructions on re-

		Form a Budget			o. 42F	1142
5.	LEASE	DESIGN	ACITA	AND	SERIAL	NO.

SUNDR	GEOLOGICAL SURVEY	/	NM 25452
(Do not use this form	Y NOTICES AND REPORTS for proposals to drill or to deepen or plug	ON WELLS back to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. Use	APPLICATION FOR PERMIT— for such	proposais.)	7. UNIT AGREEMENT NAME
WELL GAS WELL X	OTHER		8. FARM OR LEASE NAME
2. NAME OF OPERATOR Hixon Dev	elopment Company		Federal 29
3. ADDRESS OF OPERATOR	0010 F / N N	07/01	9. WELL NO.
	2810, Farmington, New Mexit location clearly and in accordance with an		10. FIELD AND POOL OR WILDCAT
See also space 17 below.) At surface			Wildcat #
7001 PM	7001 777 - 6 20 - 725	(a) D 1 O 1 i	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
/90' FNL,	790' FWL, Section 29, T25)A, K12W	Section 29, T25N, R12W
14. PERMIT NO.	15. ELEVATIONS (Show whether t	of, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	6365' GLE		San Juan NM
16.	Check Appropriate Box To Indicate I	Nature of Notice, Report, or	Other Data
NOTIC	E OF INTENTION TO:	SUBSE	QUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	(Other)	ABANDONMENT* X
REPAIR WELL (Other)	That the That's	(Note: Report resul	ts of multiple completion on Well pletion Report and Log form.)
as follow with 25 s the USGS	verbal approval to P & A f s: 1250'-1050' with 25 sa acks. Set regulation dry witnessed plugging operati iration date.	icks; 750'-550' with hole marker. Mr. Bi	25 sacks, 0-14C' ll Blackard of
as follow with 25 s the USGS lease exp	s: 1250'-1050' with 25 sa acks. Set regulation dry witnessed plugging operati	acks; 750'-550' with hole marker. Mr. Bi on. This well was d	25 sacks, 0-140' 11 Blackard of rilled across