For n 3160-5 (Nevember 1994)

## UNITED STATES

## DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

## SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

1	S	F	n	7	R	በ	5	۶

Do not use this	6. If Indian, Allottee or Tribe Name									
abandoned well.	Use Form 3160-3 (APD)	for such pro	posals							
SUBMIT IN TRIPL	SUBMIT IN TRIPLICATE - Other instructions of reverse side									
X Oil Well Gas Well [	Other		OIL CO	M. DIV.	B. Well Name at	nd No.				
	Name of Operator Central Assources				Central Bisti Unit #80					
Elm Ridge Resources, Inc.	Im Ridge Resources, Inc.				9. API Well No.					
3a. Address 3b						30-045-25343				
			05-632-3476			10. Field and Pool, or Exploratory Area Bisti Lower Gallup				
4. Location of Well (Footage, Sec., T., R 660' FNL & 1980' FEL				11. County or Parish, State						
Sec. 6-T25N-R12W		11. County of Fallon, Said								
366. 0-12014-1(1211	J. 0-12514-1(1244				San Juan County, NM					
2. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA										
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION									
Notice of Intent	Acidize Alter Casing	Deepen Fracture New Con		Production (S	Start/Resume)	Water Shut-Off Well Integrity Other				
Subsequent Report	Casing Repair Change Plans	X Plug and		Temporarily	Abandon					
Final Abandonment Notice	Convert to Injection	Plug Bac	k	Water Dispos	sal					
13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BL. Required subsequent reports shall be filed within 30 days Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed within 30 days been completed. Final Abandomment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  RIH w/bit and scrapper and 60-joints 2-3/8" tubing to top of scale liner. POOH w/tubing. RIH w/84-joints 2-1/16" tubing and 66-jts 2-3/8 tubing. End of tubing @ 4820'. R/U cementers est. circ. W/15 bbls H20, pump 50 sx Class "B" cement w/1% CaCl, 1/4# sx Celloflake. POOH w/40 jts tubing. RIH w/tubing - tag cement plug @ 4158'. POOH w/tubing. RIH w/wireline perf @ 1947'. RIH w/retainer and tubing - land @ 1885'. Pressure up csg to 500 PSI - held. Stung into retainer and started pumping outside csg @ 650 PSI - something broke. Started getting circ up casing. Closed casing- pumped 50 sx Class "B" cement inside and outside casing. POOH w/tubing. RIH/CIBP - set @ 1236'. Pressure up casing to 500 PSI - held good. pump 38 sx Class "B" cement to 745'. POOH w/tubing. RIH w/wireline perf. @ 266'. Nipple up -est circ and pump 89 sx Class "B" cement to surface inside and outside casing. Plugging complete. Witnessed by Kevin Schneider with the BLM - Farmington Office.										
	tieblik ur gustus te	dor rend i	s retelmed	er (M)						
14. I hereby certify that the foregoing is to Name (Printed/Typed)	ue and correct	Title								
Name (Printed Typed)  Trudy Grubelnik				Product	tion Technician					
Signature Milder Stube Inik			Date July 26, 2001							
	THIS SPACE	FOR FEDER	AL OR STA	TE USE						
Approved by		Tit	ile		Date					
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive th	uitable title to those rights in the su ct operations thereon.	bject lease	fice			R RECORÚ				
Title 18 U.S.C. Section 1001, makes it a cr fraudulent statements or representations as	ime for any person knowingly and	willfully to mak	ce to any depa	rtment or agency of	the United States					

(Instructions on reverse)

SM - Urrice

1 5 20(1