Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT -9 91112: 3 SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
5. Lease Designation and Serial No.

Lease Designation and Serial No. NM 070322

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT--" for such proposals. The proposals of the control of the cont

OSC ATTEICATIO	Carson Unit			
SUBM	IIT IN TRIPLICATE	3		
<u></u>	as Well Other DEGEIVI	8. Well Name and No. Carson Unit Well No. 208		
2. Name of Operator		API Well No.		
Central Resources, Inc.	SEP 1 4 1000	30-045-26378		
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area		
P.O. Box 2810, Farmington	n, New Mexico 87499 (105) (\$16) [\$15] 5 [5] [377 4 777 777 1.1 1 7 7 7 7		
4. Location of Well (Footage, Sec., T.,		Vo 11. County or Parish, State		
17 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		San Juan, New Mexico		
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO			
TYPE OF SUBMISSION TYPE OF ACTION				
	X Abandonment	Change of Plans		
X Notice of Intent	Recompletion	New Construction		
	Plugging Back	Non-Routine Fracturing		
Subsequent Report	Casing Repair	Water Shut-Off		
	Altering Casing	Conversion to Injection		
Final Abandonment Notice	Other	Dispose Water		
		(Note: Report results of multiple completion on Well		
12 D " D 1 0 1 10		Completion or Recompletion Report and Log form.)		
 Describe Proposed or Completed Oper 	rations (Clearly state all pertinent dates, including estimate	ed date of starting any proposed work. If well is		

 Describe Proposed of Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Central Resources, Inc. plans to plug and abandon the subject well as follows:

- 1) Plug will be set from the bottom perforation (1120') to the surface (36.4 cuft) by mixing and pumping 33 sks (38.0 cuft) of Class B neat cement.
- 2) After cement has set up, tag top and refill hole, if necessary.
- 3) Cut off wellhead and install a regulation dry hole marker.
- 4) Rehabilitate location as per BLM regulations.

14. I hereby centify that the foregoing is true and c	orrect			
Signed Oxility (1/1, K)	Title Production Engineer	Date	9/1/98	
Gregory E. McIntosh		_		
(This space for Federal or State office use) Approved by Spencer			CED 1 1 1000	
Approved by MS/ Dustie W. Spencer	Title	Date	SEP 1998	
Conditions of approval, if any:		_		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false fictitious or fraudulent statements or representations as to any manner within its jurisdiction.