	900/N; 9		Cı	J. ft.	t	ilev)433 GI	Spd	Spd. Cu. ft.	Comp	·	!I	Cu. ft.	Р	8	
sing S g.Perf.		w	Sx.	Int			w	S	x. Pr od. Stim.	———@——	,	w	Sx. T.		@	↑ Gas
	BO/D MCF/D_After		Hrs. SIC		<u> </u>	PSI	After			1st Del. <u>Gas</u> 1st Del. <u>Oil</u>						N S
	TOPS		NiTD		Х		Well Log			TEST DAT		. = .				
Ojo Alamo			C-103				Plat	Х		Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland			C-104				Electric Lo	•								
Fruitland			-				C-122							1		
Pictured Cliffs			Ditr				Dfa									
Chacra			Datr				Dac									
Cliff House		1					<u>ч</u>									
Menefee																
Point Lookout																
Mancos																
Gallup																T
Greenhorn																
Dakota																I
Entrada																
			161	XOV				Acres	E/320							
P • • • • • • • • • • • • • • • • • • •	Coal Co. S.					11W U	A Ope r. (.& Pro	od	. E. I	Bisti (Coal 2	1 No	<u> </u>

E. Bisti Coal 21 #1 A-21-25N-11W

Giant Explor.& Prod.



United States Department of the Interior

PRIDE IN AMERICA

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway

Farmington, New Mexico 87401 NOO-C-14-20-5245 et al. (WC) 3162.3-1.0 (019)

Giant Exploration & Production Company P.O. Box 2810 Farmington, NM 87499

JUL 9 1991

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1 East Bisti Coal 21 sec. 21, T. 25 N., R. 11 W., San Juan County, New Mexico, lease NOO-C-14-20-5245.
- 2. 2 East Bisti Coal 21 sec. 21, T. 25 N., R. 11 W., San Juan County, New Mexico, lease NOO-C-14-20-5243.
- 3. 331 Carson Unit 18 sec. 18, T. 25 N., R. 11 W., San Juan County, New Mexico, lease 14-20-603-1283.

As discussed with Earlene Bickford of your company on July 5, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Brid Johan L. Meiller

John L. Keller Chief, Branch of Mineral Resources

Enclosure

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410 BIA, Window Rock, AZ

ABANDONED LOCATION

JULI 0 1991
OIL CON. DIV.