

F

30-045-28505

02-08-91

F. Loc. 1765/N; 1520/E

Elev. 6458 GL

Spd.

Comp.

TD

PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. I. @

Csg. Perf. Prod. Stim.

T Gas
R
A
N
S

BO/D Grav. 1st Del. Gas
MCF/D After Hrs. SICIP PSI After Days GOR 1st Del. Oil

TOPS		NITD X	Well Log	TEST DATA						
Ojo Alamo		C-103	Plot X	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres E/320								

P
o
o

BasinFrCoal Co. SJ S 14 T 25N R 11W UG Over. Giant Explor. & Prod. Lse. Buena Suerte 14G Com. 1

Buena Suerte 14G Com #1

G-14-25N-11W

GIANT EXPLOR. & PROD. CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington Resource Area
1235 La Plata Highway
Farmington, New Mexico 87401

TAKE
PRIDE IN
AMERICA

NOO-C-14-20-3616 (WC)
3162.3-1.0 (019)

MAR. 16 1992

Giant Exploration & Production Company
P.O. Box 2810
Farmington, NM 87499

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 1 Buena Suerte 14G Com., Section 14, T. 25 N., R. 11 W., San Juan County, New Mexico, lease NOO-C-14-20-3616. As discussed with Earlene Bickford of your company on March 5, 1992, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

.1 Enclosure

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410
Bureau of Indian Affairs, P.O. Box "M", Window Rock, AZ 86515

ABANDONED LOCALITY

RECEIVED

MAR 17 1992

OIL CON. DIV.
DIST. 3