01

CONDITIONS OF APPROVAL, IF ANY :

PERMIT NO.

\*See Instructions On Reverse Side

APR 17 1992
AREA MANAGER

APPROVED AS AMENDED Submit to Appropriate District Office State Lease - 4 copies For Lease - 3 copies

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-102 Revised 1-1-89

## **OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

ALI EMEN ELH

SI 173 23 111 C: 10

Edgar 3.

DISTRICT I P.O. But 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210

WELL LOCATION AND ACREAGE DEDICATION PLAT 1000 Rio Brazos Rd., Aziec, NM 87410 All Distances must be from the outer boundaries of the section Operator Cisco Dugan Production Corporation Ruge Causty Und Lotter Section Township 25 North 13 West San Juan **NMPM** Actual Footage Location of Well: 1650 2310 West South feet from the line feet from the line and Ground Level Elev. Dedicated Acreage: Producing Formation Bisti Lower Gallup 80 Gallup 6350 Acres 1. Outline the acreage dedicated to the subject well by colored peacil or bachus marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and soyalty). 3. If more than one lease of different ownership is dedicated to the well, have the interest of all owners been consolidated by communitization, unitization, force-pooling, etc.? Yes ☐ No If answer is "yes" type of consolidation If answer is "no" list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if neccessary. No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interest, has been approved by the Division. OPERATOR CERTIFICATION I hereby certify that the information tained herein in true and complete to the Position Vice-President Dugan Production Corp 4-22-91 Section SURVEYOR CERTIFICATION I hereby certify that the well location shown . 1650 on this plat was plotted from field notes of 0 actual surveys made by me or under my Dugan Prod. supervison, and that the same is true and SF-078156A correct to the best of my knowledge and belief. 2310' Date Surveyed April 9, 1991 Signature & Seal of ATTERPRESENTATION Professional Surveyor RISEAU OF MEXICOLORS RISEAU METO

1500

2000

1960 2310

990 1320 1650

2440

1000

500

VI 3 1 7 3 / C 2/ 2/ 80"	
3 - Francisco Constitution	On Con
	100/2000
	200 5 5 5 50
	3 /
3272	25/ 35/ 35/
50353 33 0 V	
43535.5.5	18 200
1355 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
2 2 2	
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	To the state of th
1 2 2 20 Va	
The same of the sa	
	2 ma
3	Louis & Control of the Control of th
1 h 25 < 2 3 K / Sign	5707 2 0 2
Drill Hole	
3 5 5 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	and and and
	my n m
	Service Oil Oil Oil Well
130	w. (-S-)
	~ > ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
	10 27
.,*	a de objection of the services
	2 ( ) S
Existing Roads Exhibit E	Planned Access Road(s) Exhibit E
Vicinity of nearest town or reference pt.	Width 20' Maximum grades 1% Drainage design as required
Approx. 18 miles South of Farmington, NM	Drainage design <u>as required</u> Cuts & Fills <u>see diagram</u>
Type of surface dirt	Surfacing material <u>none</u>
Conditions good	→ Turnouts / Waterbars ☐ Culverts
	<pre></pre>
Other USGS map Moncisco Wash	Fence cuts
1966 & The Pillar 1966	Access road(s) (do) do not cross Fed/(Ind) land.
1000 0 1110 12201 1000	DUGAN PRODUCTION CORP CISCO #1