

(SURVEY IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office **Santa Fe**Lease No. **080375**Unit **Sheets**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT OFF	RECEIVED MAY 14 1963 U. S. GEOLOGICAL SURVEY WASHINGTON, NEW MEXICO
NOTICE OF INTENTION TO CHANGE LEASE	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER	SUBSEQUENT REPORT OF ABANDONING CASING	
NOTICE OF INTENTION TO RE-DRILL OR RE-ENTER WELL	SUBSEQUENT REPORT OF RE-DRILLING OR RE-ENTER	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO RE-ENTER CASING	SUBSEQUENT REPORT OF RE-ENTER	
NOTICE OF INTENTION TO NEW DRILL WELL	SUBSEQUENT REPORT OF NEW DRILL WELL	

INDICATE EARLY BY CHECK MARKS NA, N, P, M, REPORT, NOTICE, OR OTHER DATA

May 14 1963

Well No. **9-D** is located **1450** ft. from **N** line and **1815** ft. from **E** line of sec. **31****NE/4 Section 31****26N****7W****N.M.P.M.****Ballard Pictured Cliffs****Rio Arriba****New Mexico**The elevation of the derrick floor above sea level is **6409** ft.

DETAILS OF WORK

State names of and expected depths of the various sands, shows sizes, weights, and lengths of proposed casings, indicate mudding jobs, cementing points, and all other important proposed work.

Due to non-commercial production it is intended to plug and abandon this well in the following manner:

1. Spot 30 sack cement plug across open hole down tubing after making sure it is free, or shooting off.
2. Cut and pull casing from free point.
3. Spot 20 sack plug on casing stub.
4. Spot 10 sack plug in surface casing and erect 4" x 4' permanent dry hole marker.

Understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**Address **Box 990****Farmington, New Mexico**

By

Title

Petroleum Engineer