

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Indian

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR Benson-Montin-Greer Drilling Corp.
3. ADDRESS OF OPERATOR 221 Petroleum Center Building, Farmington, NM 87401
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

88 SEP 16 AM 11:21

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

660' FWL 471' FSL, Section 29, T27N R1E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
7054' GR

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla 237

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Tribal

7. UNIT AGREEMENT NAME

East Puerto Chiquito Mancos

8. FARM OR LEASE NAME

9. WELL NO.

1 (2423)

10. FIELD AND POOL, OR WILDCAT

E. p. Chiquito Mancos

11. SEC. T., R., M. OR BLK. AND
SURVEY OR AREA

Section 29, T27N R1E

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work. *

Cement plug from TD 1979' to 1790' - 28 cubic feet cement slurry (24 sacks cement).

Cemnt plug; from 1400' to surface - 190 cubic feet cement slurry (160 sacks cement).

Cement down casing head (5 1/2" x 7" annulus) 23 cubic feet cement slurry (20 sacks
cement).

Erect dry hole marker.

Restore and reseed location.

Well was plugged and abandoned - apparently operator inadvertently failed, at the
time, to file "Notice of Intent" with the Bureau of Land Management.

18. I hereby certify that the foregoing is true and correct

SIGNED

Virgil L. Stoabs

TITLE

Vice President

DATE

Sept. 15, 1988

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

SEP

*See Instructions on Reverse Side