Form 9-380

U. S. LAND OFFICE SERIAL NUMBER SF 030511 LEASE OR PERMIT TO PROSPECT ...

UNITED STATES DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

LOCATE	WELL CORRECTL		LC	JG OF	OII	. OR G	AS	WELI	L	
Company .	M 1 T3	-		4 A	dragg	AZTEC	O, NEW	MEXICO		
	ract HARRI	ngion #1		Fie	eld		Sto	to NEW	MEXICO	
	1 Sec.									
Location	999t. (NXXX) of	Line and	$\epsilon_{ m oq_t}$	EXX of	W Line	of SECTIO	H 31	Elevati	5998.51	
	formation given			(, , ,)	_	. /1 .		(T)64,10K	HOUR PELETIVE TO SEE 18Vel.	
so far as ca	n be determined	from all av	ailable r	records.	med	UXNI	han	-1.4		
Date	APRIL 12, 1	952		OIF	31160	Title	ONNE	1		
	mmary on this p		he condi	tion of the	well at :	above date.				
Commenced drilling Finished drilling April 12 April 12										
OIL OR GAS SANDS OR ZONES										
No. 1, from 2103 to 2180 P.C. No. 4, from (Denote gas by G) No. 1, from 2103 to 2180 P.C. No. 4, from (OHLO)										
							Oit-	от сом		
	No. 2, from to No. 5, from to DiST-3 No. 3, from to No. 6, from to									
IMPORTANT WATER SANDS										
No. 1, from	500	to	1000 (1	Lots of p	90 7 , N	ter)		to		
No. 2, from		to	*	N	o. 4, fro	om		to		
			CA	SING REC	CORD					
Size Wei easing per	ight Threads per foot inch	Make	Amoun	t Kind of si	ioe Cut	and pulled from	Perfo From—	To-	Purpose	
8 5/8	23 10	J-55		7 FLOA	\mathbf{r}	1 1 20 2 2 2 4 2 2 2	STATCE D	-	SURFACE	
7-11-1-1-1	16	3-55			n pries	e engliseries	वित्राह्य ह ं अद्भाव स्त्राह्य	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PRODUCTION	
		' '				A KIT I		دېدېلنده ده د د د د د د د د د د د د د د د د د	5.141.18154.c.732.	
		- 1	1	1	1	MEE!	rudalita	·		
		MUDE	ING A	ND CEMEN	TING	RECORD	'			
Size casing W	here set Num	ber sacks of cer	nent	Method use	ed	Mud gravity	Aı	mount of m	ud used	
8 5/8		-		burton						
103 5 1/2 2103 200 sacks				Helliburt on						
					1		1			
Hoaving pl	ug-Material	1		S AND AD			Danth an	L		
	Material	i		i						
accaptors				OTING RI						
Size	Size Shell used Explosive used			Quantity Date Depth shot Depth cleaned out						
WILL			ot at a	LATER D	DAIE					
*									***************************************	
				rools us		1=				
Rotary tools were used from feet to feet, and from feet to feet										
Cable tools	were used from		feet	1	feet,	, and from		feet to .	feet	
Apri:	1 12	19	52	DATES Put	to prod	ducing W	ATTING	ON HOOK	IID 10	
The pro	oduction for the	,			-	_			•	
	% water; and			1					-, ,0	
	vell, cu. ft. per 2				ns gasol	line per 1,000	cu. ft. c	f gas	DRY	
Rock p	ressure, lbs. per	sq. in	885	. ' ! -						
	! :			EMPLOYE					Drillor	
				1					,	
***************************************				1ATION R	ION RECORD				, 1)rmer	
FBOM-	то	no	TAL FEET			FORM	ATION			
									,	
3600	1600		1600			& SHALES				
1600 1970 370 Mostly shales 970 2301 133 Coal & Shale Seams										
2103 2180 77 PICTURED CLIFF SAND 2180 2240 160 DARK BROWN SHALE										
DAILA DIVAN ORALE										
		103	Pictured Cliff							
		2	180	Let	Levis Shale					
		; ! !		:						
	i			:						
		:								
	1	i		1						