Budget Bureau	No. 49-D9	BO 4
Approval expir	BS 121-31-0U.	

Form 9-881 b (April 1952)			
	_		
·			

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY Lo

indian Agency Jicarilla
Cont. #93
Allettee
Lease No.

SUNDRY N	OTICES A	IND REP	ORTS ON V	VELLS
NOTICE OF INTENTION TO DOUG	<del></del>	11		
IOTICE OF INTENTION TO DRILL IOTICE OF INTENTION TO CHANGE PLANS	e	41	T REPORT OF WATER SHUT	
OTICE OF INTENTION TO TEST WATER S		ii .	t report of shooting o t report of altering ca	I
OTICE OF INTENTION TO REDRILL OR R	ł	<u>l</u>	T REPORT OF REDRILLING	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
OTICE OF INTENTION TO SHOOT OR ACI		li i	T REPORT OF ABANDONME	The state of the state of
OTICE OF INTENTION TO PULL OR ALTE	R CASING	11	TARY WELL HISTORY	
OTICE OF INTENTION TO ABAJIDON WELL	<u> </u>	XX		
	BOVE BY CHECK MARK	NATURE OF REPO	XT, NOTICE, OR OTHER DATA	overber 5 , 19 62
Jicarilla Il No. <u>93-3</u> is locate 3/4 Sec. 33	ed 1180 ft. fro	om $\frac{N}{3}$ line a	nd 990 ft. from	E line of sec 33
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	/ KLULIYL
acco Hosa Verde	RL	o Arriba	<b></b>	ste or Territory) NOV 7 196
As many of and arrested double to the		vel is 7186	RK	DIST. 3
	jective sands; show siz ing points, and all c	ILS OF WO	RK ingths of proposed casings; roposed work)	indicate mudding jobs, coment-
ne to non-commercial praner:  Rulp water into casi be displaced Mown or Pump 150 eachs regul wiper plug, displace. Shoot off 7" casing	ing points, and all croduction it ing to make a seing. Ler coment, (a to top of a free points pot 10 sack	ILS OF WOI  Los, weights, and le  other important p  is intend  sure will  6% gel down  liner.  ot and spo-  cessent plu	RK  Ingths of proposed casings; reposed work)  In to plug this  Is dead and to  If casing fol	indicate mudding jobs, coment- well in the follow make sure coment ca
. Pump water into casi be displaced Mown or . Pump 150 eachs regul wiper plug, displace . Shoot off 7" casing . Pall 7" casing and s	ing points, and all croduction it reduction it ing to make asing. Lar commut, (a to top of a true points pot 10 mack hole surface)	ILS OF WOI  zes, weights, and le  other important p  is intend  sure will  6% gel down  liner.  ot and spo-  cement plan	RK Ingths of proposed casings; roposed work)  In to plug this is dead and to a 7" casing folk committee in to p of a sological Survey before open	well in the follow make sure coment callowed by 7° top t plug on 7° stub.