Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31 1993

RUDEALLO	ELAND MANACEMENT	Expires: March 31, 1993
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No. SF 079321
	S AND REPORTS ON WELLS drill or to deepen or reentry to a different reservo	6. If Indian, Allottee or Tribe Name
Use "APPLICATION F	OR PERMIT-" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
	TIN TRIFLICATE	Rincon Unit
1. Type of Well Oil Gas □ Well ⊠ Well □ Other		8. Well Name and No.
Well Well Other 2. Name of Operator	a Colored Do	Rincon Unit #138
Union Oil Company of California	- 1880 R 1880	9. API Well No.
3. Address and Telephone No.	(915) 685-76PT JUN 2 9 11 (D) (1915)	30-039-06933
P. O. Box 671Midland, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey D	(915) 685-7607 JUN	10. Field and Pool, or Exploratory Area
	a Comment	Bain Dakota/Mesa Verde
Unit Ltr "A" 890' FNL & 790' FEL Sec. 25,	, T-27-N, R-7-W	11. County or Parish, State
		Rio Arriba County, NM
12. CHECK APPROPRIATE BOX((s) TO INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
✓ Notice of Intent☐ Subsequent Report	Abandonment	Change of Plans
	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report		☐ Water Shut-Off
	Casing Repair	- water charton
Final Abandonment Notice	Casing Repair Altering Casing	Conversion to Injection
		Conversion to Injection Dispose Water
Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly directionally drilled, give subsurface locations and meaning the subsurface locations and meaning the subsurface locations.	Altering Casing Other State all pertinet details, and give pertinent dates, including estimated dates as a sured and true vertical depths for all markders and zones pertinent to the	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is swork.)*
Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly directionally drilled, give subsurface locations and mean Rincon Unit #138 is currently producing in the	Altering Casing Other State all pertinet details, and give pertinent dates, including estimated dates.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is swork.)*
Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly directionally drilled, give subsurface locations and measurement with the second committees of the second committee	Altering Casing Other State all pertinet details, and give pertinent dates, including estimated dat assured and true vertical depths for all markders and zones pertinent to this me Basin Dakota with perforations at 7476'-7684'. Unocal process.	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is swork.)*
Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly directionally drilled, give subsurface locations and mean Rincon Unit #138 is currently producing in the (est.) 5200'-5450' and downhole commingle approved. 14. I hereby certify that the foregoing is true and correct Signed Charlet Bleson (This space for Federal or State office use)	Altering Casing Other state all pertinet details, and give pertinent dates, including estimated dat assured and true vertical depths for all markders and zones pertinent to this me Basin Dakota with perforations at 7476'-7684'. Unocal provides the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota. The work will begin the Basin Dakota. The work will be gin the Basin Dakota. The	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is swork.)* Dians to perforate the Mesa Verde at possible, after the DHC Permit is Date06/15/99
Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly directionally drilled, give subsurface locations and mea Rincon Unit #138 is currently producing in th (est.) 5200'-5450' and downhole commingle approved.	Altering Casing Other state all pertinet details, and give pertinent dates, including estimated dat assured and true vertical depths for all markders and zones pertinent to this me Basin Dakota with perforations at 7476'-7684'. Unocal provides the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota with the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota with the Basin Dakota. The work will begin, as soon as possible to the Basin Dakota with the Basin Dakota. The work will begin with the Basin Dakota. The work will begin with the Basin Dakota with the Basin Dakota. The work will begin with the Basin Dakota with the Basin Dakota. The work will begin with the Basin Dakota with the Basin Dakota. The work will begin with the Basin Dakota. The work will begin with the Basin Dakota with the Basin Dakota. The work will begin with the Basin Dakota with the Basin Dakota. The work will begin with the Basin Dakota with the Basin Dakota with the Basin Dakota. The work will be gin with the Basin Dakota with the Basin Dakota with the Basin Dakota. The work will be gin with the Basin Dakota with	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is swork.)* Dians to perforate the Mesa Verde at possible, after the DHC Permit is

(P)