UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT


Sundry Noti	ces and Reports on Wel	S 13 P.1 1: 44	
1. Type of Well GAS	oro 1921 (a)	FILL (SEC), 161	SF 079692-B If Indian, All. or Tribe Name
2. Name of Operator	HILL DEC	2 7 1909 277.	Unit Agreement Name SAN JUAN 27-5 UNIT
BURLINGTON RESOURCES OIL	GAS COMPANY	on. Div. s. s. s.	Well Name & Number
3. Address & Phone No. of Operat PO Box 4289, Farmington, NM	or		SAN JUAN 27-5 UNIT #7 API Well No. 300390694300
4. Location of Well, Footage, Se 790' FSL, 890' FWL Sec. 27, 1			Field and Pool Tapacito PC County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INI			R DATA
Type of Submission _X_ Notice of Intent	Intent Abandonment Change of Plans New Construction		
Subsequent Report	Plugging Back _ Casing Repair _	Non-Routine Water Shut o	Fracturing off
Final Abandonment	Altering Casing _ _X_ Other - Restimula	Conversion t	
1. MOL and pressure test 2. Acidize and foam fract 3. Clean out well. 4. Return well to product	casing. ture treat PC zone.		
14. I hereby certify that the Signed Condition of Approval, if any:	Title <u>Regulatory A</u> e Office use)	<u>dministrator</u> Da	te <u>12/08/99</u>

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

SAN JUAN 27-5 UNIT #75

Section 27 M, T-27 -N R-05 -W Rio Arriba, New Mexico

Tapacito Pictured Cliffs Field Wellbore Schematic



File: Q:\area\!pcteam\2000\welldata\Rigless Slimhole\Wellbore Diagram.doc