OIL CONSERVATION DIVISION

Page Revised 10/01/7

This form is not to be used for reporting pecker leakage tests in Southeast New Mexico

NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator	UNION	OIL	COMPAN	Y OF	CAL I FOR	NIA	Lease	RIN	ICON UN	IIT	We No		
•											inty	RIO ARRIBA	
	name of reservoir or pool					TYPE OF PROD. (Oil or Gae)		METHOD OF PROD. (Flow or Art. Lift)		D.	PROD. MEDIUM (Tbg. or Cag.)		
Upper Completion							GAS		FLOW		TUBING		
Completion BLANCO MESA VERDE							GAS			FLOW		TUBING	
					PRE-FL	ow s	HUT-IN	PRESSURE	DATA				
Upper Completion	Hour, date s APRIL	07,	1996	11:15/	gth of time sh	3 [DAYS	Si press. psi	TBG 1			(Yes or No) NO	
Lower Completion	Hour, date at		1996	11:15/	th of time shi		DAYS.	SI press. psi	TBG 2	40	Stabilized?	(Yes or No) NO	
						FLO	OW TEST	NO. 1					
Consmenced	et (hour, dat	•)* A	PRIL 1	0, 199	96 11:2	MAOS		Zone pro	ducing (Upp	er or Lowert L	OWER		
TIME (hour, date)		LAPSED TIME		Upper (PRESSUI Upper Completion		r Completion		PROD. ZONE TEMP.		REMARKS		
04/11/96		24 HRS T		TBG 1	SG 115 BG 115 T		70	61°		Q = 133 MCF/D			
04/12/96				ı.	SG 120 BG 115 T		75	51° (Q) = 156 MCF/D		
													
									in the second		ಟ್ (<u>)</u> 	·	
										7 2 1966 1			
								<u></u>		·			
Productio	n rate du	uing tes	st				•					•	
Oil:			BOPI	D based	on		_ Bbls. ic	ı	Hours.	G	rav	GOR	
Gas:					MCFF	D; T	sted thru	(Orifice o	r Meter):	:			
					MID-TE	ST SH	UT-IN PI	RESSURE 1	DATA				
Upper Completion				Lengt	Length of time shut-in			SI press. psig			Stabilized? (Yes or No)	
Lower Mour, date shut-in			Lengt	Length of time shul-in			SI press. paig			Stabilized? (Yea or No)		

(Continue on reverse side)

FLOW TEST NO. 2

Lower Completion

PRESSURE

Upper Completion

Zone producing (Upper or Lowert

REMARKS

PROD. ZONE

TEMP

			<u> </u>		I	
·						
·						
	1 1					
roduction r	ate during test					
	-			•		
)il:	BOPD	based on	Bbls. in	Hours.	Grav	GOR
las:		VCE	D. Tarak Abas	(O-:G)()		•
· — — — — — — — — — — — — — — — — — — —		MCFF	D: Tested thin (Office of Meter)		· · · · · · · · · · · · · · · · · · ·
emarks: _						
						
hereby certi	ly that the information	n herein containe	d is total and an-	salara en elsa basa	af !!!	
				ipiete to the best	of my knowledge.	
pproved	Johnny Robins	un	. 19 Or	perator UNION	OIL COMPANY OF C	ALIFORNIA DBA UNG
New Mexic	o Dil Conservation Div	vision			Min	
	APR 2 2 199	36	Ву			
у				R.L. Co	aine tion Foreman	
y	DEPUTY OIL & GAS IN	SPECTOR		le Produc	cron roreman	
itle			Da	April :	19, 1996	

NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever temedial work has been done on a well during which the packer or the tubing have been distrurbed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.
- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization: Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 5. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.
- 6. Flow Test'No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except

that the previously produced zone shall remain shut in while the zone which was previously shut in it produced.

7. Pressures for gas-zone tests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.

24-hour oil zone terts: all pressures, throughout the entire tert, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each tert, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 13 dars after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Division on Northwest New Mexico Packer Leakage Test Form Revised 10-01-78 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).

RLC/sk1

Communeed at (hour, date) ##

LAPSED TIME

SINCE ##

TIME

(hour, date)