



**NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178 Fax (505) 334-6170

GARY E. JOHNSON
GOVERNOR

JENNIFER A. SALISBURY
CABINET SECRETARY

December 16, 1996

Ms Dolores Diaz
Burlington Resources O&G Co
PO Box 4289
Farmington NM 87499

RE: Packer Leakage Retests

Dear Dolores:

Please find enclosed the inconclusive 1996 Packer Leakage Tests on the following wells:

San Juan 27-4 Ut #13	G-20-27N-04W	30-039-06992
San Juan 27-4 Ut #36	K-36-27N-04W	30-039-06810
Decker #4A	O-10-32N-12W	30-045-23332

These wells need to be rescheduled and retested in a way that proves separation and shuts both zones in for a minimum of three days. Flow the higher pressured zone until the pressure decreases enough to determine if there is zone separation. Please notify this office a least 24 hours before tests are conducted so that we may provide a witness, and if you have any questions please feel free to call me at 334-6178.

Sincerely,

Ernest Cardona
Deputy O&G Inspector

EC/sh

Encs

cc: Well Files
EC File