

30-039-07001

F. Loc. 990/N; 1030/E Elev. 6518 DF Spd. 10/8/54 Comp. 11/16/54 TD. 5550 PB.
 Casing 9-5/8 @ 170 W. 125 Sx. Int. @ W Sx. Pr. 7 @ 4810 W. 500 Sx. T. 2 @ 5500
 Csg. Perf. SOF 4810-5048 w/15200 G, 8000 #; SOF 5314-5550 w/14160 G, 10500 # T r 59
 I.P. 2827 MCF/D After 3 Hrs. SICP 1110 PSI After 17 Days GOR Grav. Ist Del. 2/15/55 °EPNG

TOPS		NITD	Well Log	TEST						DATA	
				Schd.	PC	Q	PW	PD	D	Ref. No.	
Kirtland	2646	C-102	Plat								
Fruitland	3017	C-103	Electric Log								
Pictured Cliffs	3180	C-104	C-110	10/24/55	1024	474	547	512	492	#513	
Cliff House	4884	C-122-B		6/7/56	1035	473	645	518	551		
Menefee	4986	Ditr 7/2/54	Dfr 5/2/57		777		550	574	419		
Point Lookout	5396	Datr 11/16/44	Dac 9/23/64		992	128	125	456	159		
Mancos		Remarks		10/4/58	901	747	556	451	861	#4121	
Tocito				9/15/58	801	529	551	405	540		
Dakota				7/3/61	809	524	551	405	540		
Morrison											
Entrada											
PCD	3338			3/8/64	802	313	492	642	209	#8001	

P
o
i
Blanco MV Co. RA s 22 T. 27N R. 6W U.A. Over EPNG Lse Rincon Unit No. 29