

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
MERIDIAN OIL

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
915' FNL, 933' FWL, Sec. 24, T-27-N, R-7-W, NMPM

5. Lease Number  
SF-079298C

6. If Indian, All. or  
Tribe Name

Unit Agreement Name

Well Name & Number  
Ripley #1

API Well No.  
30-039-07007

10. Field and Pool  
So Blanco Pict. Cliffs

11. County and State  
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other -	

13. Describe Proposed or Completed Operations

12-12-94 MIRU. Establish circ w/10 bbl wtr. ND WH. NU BOP. POOH w/125 jts 1 1/4" tbq. TIH w/5 1/2" cmt retainer, set @ 3096'. SDON.

12-13-94 Establish circ w/60 bbl wtr. PT csg to 500 psi, OK. Sting into cmt retainer. Plug #1: pump 44 sx Class "B" neat cmt below cmt retainer and 34 sx above cmt retainer to 2800'. POOH. Perf 4 sqz holes @ 2638'. POOH. Establish circ. TIH w/5 1/2" cmt retainer, set @ 2545'. Plug #2: pump 149 sx Class "B" cmt below cmt retainer @ 2330-2638' and 25 sx above cmt retainer to 2330'. POOH to 1238'. Perf sqz holes @ 1282'. TIH w/5 1/2" cmt retainer, set @ 1238'. SDON.

12-14-94 Established circ. Plug #3: pump 54 sx Class "B" neat cmt below cmt retainer, @ 1182-1282', and 7 sx above cmt retainer to 1177'. Sqz off at 1000 psi. POOH. TIH. Perf 2 sqz holes @ 148'. POOH. Establish circ down 5 1/2" csg and out bradenhead w/12 bbl wtr. Plug #4: pump 87 sx Class "B" neat cmt down 5 1/2" csg to 148' and out bradenhead. Circ 1 bbl cmt out bradenhead. WOC. ND BOP. Cut off WH. Install dry hole marker w/10 sx cmt. RD. Well plugged and abandoned 12-14-94.

Approved as to posting of the well log.  
Likely under bond is retained until

14. I hereby certify that the foregoing information is completed.

Signed [Signature] Title Regulatory Affairs Date 12/21/94

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

CONDITION OF APPROVAL, if any:

APPROVED

DEC 28 1994

WATER MANAGEMENT

NMOCD