UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED BLM

Sundry Notices and Reports on Wells		
96 SEP 25 PII 3	<u>3: 18</u>	
	5.	Lease Number
1 Type of Well 070 FARMINGTON	i. NM	SF-079391
1. Type of Well GAS	.6.	If Indian, All. or Tribe Name
ممی		iribe Name
	7.	Unit Agreement Name
2. Name of Operator		
BURLINGTON RESOURCES		
RESOURCES OIL & GAS COMPANY		San Juan 27-5 Unit
	8.	· · · · · · · · · · · · · · · · · · ·
3. Address & Phone No. of Operator		San Juan 27-5 U #47
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	
4. Location of Well, Footage, Sec., T, R, M	1.0	30-039-07049 Field and Pool
1500'FSL, 1750'FWL, Sec.18, T-27-N, R-5-W, NMPM	10.	So Blanco Pict Cliffs/
£		Blanco Mesaverde
1	11.	County and State
		Rio Arriba Co, NM
12 CUECK ADDRODDIAME DOV MO THOUGHT NAMEDE OF NOMEON DEPONDS OF		
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, O Type of Submission Type of Action	THER	DATA
X Notice of Intent Abandonment Change o	f Pla	ns
Recompletion New Cons	truct	ion
Subsequent Report Plugging Back Non-Rout	ine F	'racturing
Casing Repair Water Sh		
Final Abandonment Altering Casing Conversi X Other - Pay add	on to	Injection
x Other - ray add		
13. Describe Proposed or Completed Operations		
It is intended to add pay to the Mesaverde formation of the a cast iron bridge plug above the Point Lookout, per treating the Cliff House/Menefee. The well will then	fora	ting and fracture
		ECEIVED
	មមួ	OCT 1 a sour III
	<u> </u>	
	<u> </u>	COM. DIV. DIST. 3

14. I hereby certify that the foregoing is true and correct.		·
Signed May Drakhuld (LLL3) Title Regulatory Adminis	trato	r Date 9/24/96
(This space for Federal or State Office use) APPROVED BY	e	
_ 	<u>ئ</u> ي <u>د</u>	J V ED
	ָ ֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֖֓֞	2.1996 p Hanader
	Ch	p Hanader
NMOCD for		1

San Juan 27-5 Unit #47 Unit K, Sec 18, T-27-N, R-5-W

Latitude: 36-34-15 1500' FSL, 1750' FWL Location: 107-24-11 Longitude: Rio Arriba County, NM ES. GRN. Ind. ML, TS Logs Run: Blanco MV/Blanco PC South **Current Field:** 11/24/59 Completed: 3/9/59 Spud: 6464' Elev KB: 6454' Elev GL: 5491' PBTD: TD: 5591' CASING RECORD: Cmt Top Depth Set Cmt Vol Weight <u>Grade</u> Hole Size Casing Size 80 sks Surf (Circ) 32.75# SW 173' 10-3/4" 2820' (TS) 90 sks 3386' 26.4# J-55 9-5/8" 7-5/8" LINER RECORD: Cmt Top Cmt Vol **Grade** Depth Set Weight Hole Size Casing Size 3339' - 5586' 572 sks 3339' (TS) J-55 15.5# 6-3/4" 5-1/2" **TUBING RECORD:** Other <u>Depth</u> Depth Set **Joints** <u>Grade</u> **Tubing Size** Weight 5419 171 J-55 2-3/8" 4.7# 102 3258' 1-1/4" 2.4# 10 RD 3295 Guiberson AG Pkr. **FORMATION TOPS:** 5375'

Ojo Alamo 2468' Pictured Cliffs 3200' Pt Lookout 5375
Kirtland 2718' Cliffhouse 4851' Gallup —
Fruitland 3003' Menefee 5055' Dakota —

Completions:

Mesaverde - PL

Perfs: 5376-80, (4 spf) 5388-5400, 5406-20, 5450-64, 5490-5502 (2 spf)

Frac: 60,000 gal water & 60,000# sand (20/40). SIWHP: 1020 psi AOF: 3350 MCFD

Pictured Cliffs

Perfs: 3210-20, 3248-58, 3268-78 (2 spf). Frac: 35,000 gal water & 35,000# sand (10/20). SIWHP: 1006 psi AOF: 3242 MCFD

Cementing Information

10-3/4" casing cemented w/ 80 sks regular cement, 2% gel, 40 cu ft Strata-Crete"6", 2% gel.

7-5/8" casing cemented w/ 20 sks regular cement, 20 sks Pozmix, 2% gel, 1/4 cu ft Strata-Crete "6" /sk, followed by 50 sks neat.

5-1/" casing cemented w/ 161 sks regular, 161 sks Pozmix, 1/8# Flocele /sk, 6% gel, followed by 50 sks neat; liner top squeezed w/ 100 sks neat (over displaced); squeezed w/ 100 sks neat.

Workover History:


5/15/59 While attempting to repair leaking packer, fish was left in hole (2-3/8" tubing and packer). Top of fish is 5491'.

LLL:rjp 9/18/9€

SAN JUAN 27-5 UNIT #47

Unit K, Section 18, T-27-N, R-5-W Lat. 36-34-15, Long. 107-24-11

CURRENT WELLBORE SCHEMATIC



TD @ 5591' PBTD @ 5491'