

UNITED STATES DEPARTMENT OF THE INTERIOR

F. O. Box 765 Fareington, New Yexico

May 9, 1955

El Paso Natural Gas Company Box 997 Farmington, New Mexico

Re: New Mexico 03521

Gentlemen:

Receipt is acknowledged of your "Notice of Intention to Drill" dated May h, 1955 covering your well No. 12 San Juan 28-7 Unit in Nel sec. 17, T. 27 No. Ro 7 Wo, R. M. P. Mo, Bio Arriba County, New Hexico, So. Blanco pool.

Tour proposed work is hereby a proved subject to compliance with the provisions of the "Oil and Gas Operating Regulations" revised May 25, 1922, a copy of which will be sent to you on request, and subject to the following conditions:

- 1. Drilling operations so authorized are subject to the attached sheet for general conditions of approval.
- 2. Furnish copies of all logs.

Very truly yours.

(Orig. Sgd.) A. P. KLEELING.

A. P. Kleeman Acting Edstrict Engineer

A Kleenamine





(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land	Office	Ken	Mark Le	0
Loase	No	035	21	
Unit	San	Junt	1 28-7	Uni
	14-0	xi-Ba	11-459	

SUNDRY NOTICES AND REPORTS ON WELLS

		X	CURRENCE DEPOSIT OF WATER CHUT OFF	
	NTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF.	
	NTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.	
	NTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.	-
	NTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPORTS	.0
	NTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDON TON	BAE
	NTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	WEX.
OTICE OF I	NTENTION TO ABANDON WELL		CEOTOR NEW	<u> </u>
	(INDICATE ABOVE BY CHECK)	MADK NAT	SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPORT SUBSEQUENT REPORT OF ABANDON AND ADMINISTRATION ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION AND ADMINISTRATION ADMINISTR	
	(INDICATE ABOVE BY CITICAL)	MARKIN IVA	FARMI	
			Mecy 4,	955
			, 1	/
	is located 1550 ft. f	TOTAL	inc and men (W) me of section (W)	7.:
(1/4 Se				
. Flan		nnty or Su	to Arriba Mey Mexico bdivision) (State or Territory)	-
	(Field) (Con	ant, or bu	(State of Economy)	
1	ion of the derrick floor above se	a loveal	: 6560 a	
e elevat	ion of the defrick floor above se	a icvei	15 1c.	
	DE	TAITS	OF WORK	
	DE	IAILS	OF WORK	
ite names o	of and expected depths to objective sands; sho	ow sizes, v	veights, 'and lengths of proposed casings; indicate mudding jobs, r rimportant proposed work)	cemen
	ing points, and	d all other	rimportant proposed work)	
t is in cols to md-oil	ing points, and a very standard to drill a well the casing point and to i fracture the entire pay Program: 9 5/8" at 120' with 125	an other	e Pichared Cliff formation using rot the pay section with cable tools an on. Total Depth 3085'.	ary i to
t is in cols to mad-oil	ing points, and a very standard to drill a well the casing point and to i fracture the entire pay Program: 9 5/8" at 120' with 125	an other	e Pichured Cliff formation using rot the pay section with cable tools an on. 'fotal Depth 3085'.	ary i to
t is in cols to and-cil	riended to drill a well the casing point and to fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75	an other aru th dor111 suct1	e Pichared Cliff formation using rot the pay section with cable tools an on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks Formix.	ary i to
t is in one to be in a sing l	ing points, and it is the casing point and to it fracture the entire pay Program: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75	an other aru th dor111 suct1	e Pichared Cliff formation using rot the pay section with cable tools an on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks Formix.	ary i to
is in in tools to mid-oil sing !	riended to drill a well the casing point and to fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75	an other aru th dor111 suct1	e Pichared Cliff formation using rot the pay section with cable tools an on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks Formix.	ary i to
is in in cols to main oil sing l	ing points, and it is the casing point and to it fracture the entire pay Program: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75	an other aru th dor111 suct1	e Pichared Cliff formation using rot the pay section with cable tools an on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks Formix.	ary i to
is in in tools to mai-oil sing !	riended to drill a well the the casing point and to fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicate 03521.	an other aru th drill sucti sucks sucks	e Pichared Cliff formation using rot the pay section with cable tools and on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks lossix. to this well.	ary i to
is in in to the sing line He	riended to drill a well the the casing point and to fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicate 03521.	an other aru th drill sucti sucks sucks	e Pichared Cliff formation using rot the pay section with cable tools an on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks Formix.	ary i to
is in in cols to cols	ing points, and the chains to the cosing point and to i fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicated the 03521.	and the art the dorill spection and the special and t	e Pichared Cliff formation using rot the pay section with cable tools and on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks lossix. to this well.	ary i to
is in in the last of the last	riended to drill a well the the casing point and to fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicate 03521.	and the art the dorill spection and the special and t	e Pichared Cliff formation using rot the pay section with cable tools and on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks lossix. to this well.	ary i to
t is in pole to be in a limit of the limit o	ing points, and the chains to the cosing point and to i fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicated the 03521.	and the art the dorill spection and the special and t	e Pichared Cliff formation using rot the pay section with cable tools and on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks lossix. to this well.	ary i to
t is in one to be the like the like like like like like like like lik	riended to drill a well the the casing point and to fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicated that this plan of work must receive approximate that this plan of work must receive approximate that the plan of work must receive approximate the plan of work must receive app	and the art the dorill spection and the special and t	e Pichared Cliff formation using rot the pay section with cable tools and on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks lossix. to this well.	ary i to
is in in the last of the last	riended to drill a well the the casing point and to fracture the entire pay Progres: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicated that this plan of work must receive approximate that this plan of work must receive approximate that the plan of work must receive approximate the plan of work must receive app	and the art the dorill spection and the special and t	e Pichared Cliff formation using rot the pay section with cable tools and on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks lossix. to this well.	ary i to
is in the sing I	ing points, and it is the casing point and to the casing point and to fracture the entire pay. Program: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicate 03521. Indeed that this plan of work must receive approximate the flat of the flat o	and the art the dorill spection and the special and t	e Pichared Cliff formation using rot the pay section with cable tools and on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks lossix. to this well.	ary i to
is in the sing I	ing points, and it is the casing point and to the casing point and to fracture the entire pay. Program: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicate 03521. Indeed that this plan of work must receive approximate the flat of the flat o	and the art the dorill spection and the special and t	Pictained (lift formation using rot the pay section with cable tools and on. fotal liepth 3055. regular count circulated to surface regular count, 75 secks locals. to thus well. By A. P. Charles may be common Petroleum Engineer	ary i to
t is in the pole to be ing I will be in I wi	ing points, and it is the casing point and to the casing point and to fracture the entire pay. Program: 9 5/8" at 120' with 125 5 1/2" at 3020' with 75 1/4 of Section 17 is dedicate 03521. Indeed that this plan of work must receive approximate the flat of the flat o	and the art the dorill spection and the special and t	e Pichared Cliff formation using rot the pay section with cable tools and on. Total Hepth 3085'. regular count circulated to surface regular count, 75 secks lossix. to this well.	ary i to