UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		5.	Lease Number
		٠.	SF 07/019/49
Type of Well		6.	
GAS			Tribe Name
GAL			
		7.	Unit Agreement Na
Name of Operator			San Juan 28-6 Uni
BURLINGTON			
BURLINGTON RESOURCES			
		8.	
Address & Phone No. of Oper		•	San Juan 28-6 U
PO Box 4289, Farmington, N	M 87499 (505) 326-9700	9.	API Well No.
		1.0	30-039-07137 Field and Pool
Location of Well, Footage,		10.	Blanco MV
0' FNL, 1100'FEL, Sec./9, T-	27-N, R-6-W	11	County and State
		11.	Rio Arriba Co.,
			ALU ALLIDA CO.,
. CHECK APPROPRIATE BOX TO I	INDICATE NATURE OF NOTICE.	REPORT, OTHER	DATA
Type of Submission	Type of Action		
x Notice of Intent	Abandonment	Change of Pl	
	Recompletion	New Construc	tion
Subsequent Report	Plugging Back	Non-Routine	Fracturing
	Casing Repair	Water Shut o	ff
			
Final Abandonment	Altering Casing	Conversion t	o Injection
Describe Proposed or Com It is intended to remove	Altering Casing X_ Other -remove packet mpleted Operations the packer from the subjections	Conversion t	o Injection
Describe Proposed or Com	Altering Casing X_ Other -remove packet mpleted Operations the packer from the subjections	Conversion to	o Injection

San Juan 28-6 Unit #11

Packer Retrieval General Procedure

Inspect location and install and/or test rig anchors. Comply with all BLM, NMOCD, Forestry, and MOI rules and regulations. BE SAFE.

All vendors/service companies on location will be responsible for protection of the environment. Any questions call Steve Campbell 326-9546.

Blow down tubing. Do not kill well. NU full lubricator & test to wellhead pressure. RU wireline and set tubing plug in 1.81" F-nipple @ 5458'. Tubing should be dead.

- MIRU. Hold Safety Meeting. Place fire and safety equipment at strategic locations. Obtain and record all wellhead pressures. NU relief line to flowback tank. ND WH, NU BOP. Test BOP to 3000 psi. Add spacer spool to top of BOP.
- PU tubing to release 4 1/2" Baker Model R-3 Packer. Lower tubing slightly to engage J-pin to J-slot (this process prevents packer resetting during trip). Refer to Baker specialist on deck.
- 3. TOOH w/ 167 jts 2 3/8" 4.7# J-55 EUE tbg, 1.87" Model L sliding sleeve, 1 jt 2 3/8" 4.7# J-55 EUE tbg, and pull 4 1/2" Baker Model R-3 Packer into the 6' spacer spool. Visually inspect, tally, and stand back.
- 4. Shut pipe rams and open 2" csg valves to prevent pressure buildup.
- 5. Unscrew stripping heading assembly and pull stripping rubber and packer above stripping head assembly.
- 6. Install tbg slips. Remove and LD packer and sliding sleeve.
- 7. Screw back onto tbg string in stripping head assembly w/ tbg joint wedged in stripping rubber.
- 8. Screw stripping rubber back onto the stripping head assembly.
- Open pipe rams and continue to TOOH w/ 39 jts 2 3/8" 4.7# J-55 EUE tbg, 1.81" F-nipple, and 1 jt 2 3/8" 4.7# J-55 EUE tbg. Visually inspect, tally, and stand back. Visually inspect, tally, and stand back. LD Packer and sliding sleeve. (151 jts total) .
- 10. Rabbit and TIH w/ exp check, 1 jt 2 3/8" 4.7# J-55 EUE tbg, 1.81" F-nipple (set @ 5480'), 208 jts 2 3/8" 4.7# J-55 EUE tbg. Land tbg @ 5513'.

San Juan 28-6 Unit #11

Packer Retrieval

General Procedure

Inspect location and install and/or test rig anchors. Comply with all BLM, NMOCD, Forestry, and MOI rules and regulations. BE SAFE.

All vendors/service companies on location will be responsible for protection of the environment. Any questions call Steve Campbell 326-9546.

12. ND BOP. NU WH. Pump off check. Swab well if necessary. Contact Ward Arnold (326-9846) in Production Operations for well tie-in. RDMO.

Recommended:

Summer Engineer II

Approved:

Regional Team Leader

Approved:

Drilling Superintendent

SAN JUAN 28-6 UNIT #11

Blanco Mesaverde
Unit A, Section 9, T27N, R6W
Rio Arriba Cty, NM

Elevation: 6250' GL, 6263' KB Date Spud: 9-10-54

