submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	ces and Reports on Wells	
		5. Lease Number
		SF-079393
. Type of Well		6. If Indian, All. or
GAS		Tribe Name
G.10		s whit becoment Name
		7. Unit Agreement Name
. Name of Operator	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
BURLINGTON RESOURCES OIL 8		San Juan 27-5 Unit
RESOURCES OIL	E GAS COMPANY MAR 2000	38. Well Name & Number
		SAN JUAN 27-5 UNIT #
. Address & Phone No. of Operat	97499 (505) \$26-9700 CON DIV	9. API Well No.
PO Box 4289, Farmington, NM	8/499 (505) 3 DIST. 3	300390715800
S 11 13 Francis Co	T P M	10. Field and Pool
1. Location of Well, Footage, Se 800' FSL, 1050' FWL Sec. 5, T	T-27-N. R-5-W, NMPM 2 / 2000 R.	Tapacito PC/Blanco M
800. 12T' TO20. LMT Sec. 2' 1	الماد	11. County and State
		Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO IN	DICATE NATURE OF NOTICE, REPORT, C	THER DATA
Type of Submission	Type of Action	
<u>X</u> Notice of Intent		struction
		tine Fracturing
Subsequent Report		
-1 2 2 1 1 mm	Casing Repair Water Sh	
Final Abandonment	X Other - Re-Stimulation	-
13. Describe Proposed or Comp	leted Operations	
		-fa Proceure test
Pull 1 1/4" tbg, 2 3/8" t	bg, and pkr. Set RBP above PC pe	orfa Selectively perf
casing Retrieve RBP abo	ove PC perfs. Set CIBP above MV p	nacker and frac string.
cabing.	ies. Set RBP above MV peris. Run	pacher and reserve
- • • • • • • • • • • • • • • • • • • •	not formation Petrieve R	BP and drill CIBP. Clean
and frac by-passed MV zon	- Desa DC tormation Reffieve K	be and diffi cibi.
and frac by-passed MV zon	s. Frac PC formation. Retrieve R ', 4.70#, J-55, EUE tubing and set	be and diffi cibi.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8"	s. Frac PC formation. Retrieve R , 4.70#, J-55, EUE tubing and set	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8"	s. Frac PC formation. Retrieve R , 4.70#, J-55, EUE tubing and set	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application	s. Frac PC formation. Retrieve R , 4.70#, J-55, EUE tubing and set le commingled after the workover a ion for down-hole commingling is b	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8"	s. Frac PC formation. Retrieve R , 4.70#, J-55, EUE tubing and set le commingled after the workover a ion for down-hole commingling is b	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application	s. Frac PC formation. Retrieve R , 4.70#, J-55, EUE tubing and set le commingled after the workover a ion for down-hole commingling is b	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application	s. Frac PC formation. Retrieve R , 4.70#, J-55, EUE tubing and set le commingled after the workover a ion for down-hole commingling is b	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application	s. Frac PC formation. Retrieve R , 4.70#, J-55, EUE tubing and set le commingled after the workover a ion for down-hole commingling is b	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application the New Mexico Oil Cor	s. Frac PC formation. Retrieve R., 4.70#, J-55, EUE tubing and set le commingled after the workover a ion for down-hole commingling is buservation Division.	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application the New Mexico Oil Cor	s. Frac PC formation. Retrieve R , 4.70#, J-55, EUE tubing and set le commingled after the workover a ion for down-hole commingling is b	@ approximately 5733'.
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application to the New Mexico Oil Cor	e foregoing is true and correct.	@ approximately 5733'. and returned to being submitted
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application the New Mexico Oil Cor	s. Frac PC formation. Retrieve R., 4.70#, J-55, EUE tubing and set le commingled after the workover a ion for down-hole commingling is buservation Division.	@ approximately 5733'. and returned to being submitted
and frac by-passed MV zon Set packer above PC perfs out wellbore. Run 2-3/8" The well will be down-hol production. An application to the New Mexico Oil Cor	e foregoing is true and correct.	or Date 1/26/00

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.