# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREA	AU OF LAND MANAGEMENT	
Sundry N	Notices and Reports on Wells	
1. Type of Well GAS	DEGLIVE Nun 1 7 1996	5. Lease Number  SF-079491  6. If Indian, All. or  Tribe Name
2. Name of Operator MERIDIAN OIL	OIL CON. DIT	7. Unit Agreement Name San Juan 27-5 Unit
3. Address & Phone No. of Ope		8. Well Name & Number San Juan 27-5 U NP #5
4. Location of Well, Footage, 1040'FNL, 990'FEL, Sec.1,	, Sec., T, R, M	30-039-07205  10. Field and Pool Blanco Mesaverde  11. County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO	INDICATE NATURE OF NOTICE, RE	PORT, OTHER DATA CO 12
Type of Submission _X_ Notice of Intent Subsequent Report Final Abandonment	Type of Action           Abandonment         Cl           Recompletion         No           Plugging Back         No           Casing Repair         Was	
13. Describe Proposed or Co	ompleted Operations	- C
producing area. The Kick-Off Open-Hole Section will be 22 will remain within the San Ju Deviation Report that include the existing wellbore. It is intended to workover the TOOH w/ tubing. Set 5-1/2" Mesaverde perforations with	F Point of the well will be @ 680' (TVD); and the Maximum Verlan 27-5 Unit. Subsequent sund less the mathematical maximum one well in the following manner cement retainer 50' above Mes 130 sx Class "B" cement (100%)	averde formation @ 5904'. Squeez excess). Run CBL/CCL/GR. Set 7
4370'. A window will be cut TD of 6650' with a 6-1/4" hol TD to surface and cemented cellophane, 3 pps Gilsonite	in the $7-5/8$ " casing and the le. At that time, $4-1/2$ " $10.5$ 0 with $287$ sx $50/50$ Class "B". The Mesaverde will be se	ck will then be set in the well well will be sidetracked to a ne 0# K-55 STC casing will be run from Poz w/ 0.3% dispersant, 1/4 prelectively perforated and fracture will be returned to production.
Signed leaffy had her	the foregoing is true and correction (KAS8) Title Regulatory Ac	
(This space for Federal or St		Date
APPROVED BY CONDITION OF APPROVAL, if any	Title	APPROVED
		JUN 0 6 1996

DISTRICT MANAGE

# San Juan 27-5 Unit NP #55 Unit A, Sec 1, T-27-N, R-5-W

PBTD:

6510'

Location: 1040' FNL, 990' FEL Latitude: 36-36-32 Rio Arriba County, NM Longitude: 107-18-11

Current Field: Blanco MV Logs Run: ES, GRN, Ind. TS Spud: 5/31/60 Completed: 7/21/60 Elev GL: 7320' Elev KB: 7330' 6560'

CASING RECORD:

TD:

Hole Size Casing Size Weight Grade Depth Set Cmt Vol Cmt Top 15" 10-3/4" 32.75# SW 292' 339 cu ft Surf 9-7/8" 7-5/8" 26.4# J-55 4413' 130 sks

LINER RECORD:

Hole Size Casing Size Weight Grade Depth Set Cmt Vol Cmt Top 6-3/4" 5-1/2" 15.5# J-55 4373' - 6561' 220 sks 4373'

**TUBING RECORD:** 

**Tubing Size** Weight Grade Depth Set Joints Other Depth 4.7# J-55 8 rd 6491' 200

**FORMATION TOPS:** 

Ojo Alamo 3615' Pictured Cliffs 4128' Pt Lookout 6348'

Kirtland 3724' Cliffhouse 5952' Gallup Fruitland 3935' Menefee 6000' Dakota

Completions:

Mesaverde-CH/Men/PL

5954-62, 5986-98, 6172-6200, 6220-28, 6366-90, 6428-42, 6466-80'

70,000# sand, 60 balls and 70,000 gai water

990 1187

#### **Cementing Information**

#### Workover History:


Re-perforated Mesaverde and re-fractured w/ 50,000# sand, 60 balls, and 47,900 gal water

LLL:rjp 5/15/96

# **SAN JUAN 27-5 UNIT NP #55**

Unit A, Section 1, T-27-N, R-5-W Lat. 36-36-32, Long. 107-18-11

## **CURRENT WELLBORE SCHEMATIC**



TD @ 6560' PBTD @ 6510'



# United States Department of the Interior

#### **BUREAU OF LAND MANAGEMENT**

Farmington District Office 1235 La Plata Highway Farmington, New Mexico 87401

Attachment to Notice of Re: Sidetrack

Intention to Workover Well: 55 San Juan 27-5 Unit NP

### **CONDITIONS OF APPROVAL**

- 1. An additional cement plug is required from 4463' to 4370' inside the casing. (7-5/8" csg. set at 4413')
- 2. Mike Flaniken with the Farmington District Office is to be notified at least 24 hours before the workover operations commence (505) 599-8907.