

1000

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved
by the Bureau of Land Management
on 10-1-66

Form approved
by the Bureau of Land Management
on 10-1-66

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Aztec Oil & Gas Company		8. FARM OR LEASE NAME Companero
3. ADDRESS OF OPERATOR P.O. Drawer 570, Farmington, New Mexico		9. WELL NO. #1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1190 FNL & 1490 FEL, Section 12-27N-4W		10. FIELD AND POOL, OR WELDCAT Basin Dakota
14. PERMIT NO.		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Section 12-27N-4W
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH OR STATE Rio Arriba New Mexico


16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TECH. WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
PUMP AND TREAT	☐	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
ABANDON*	☒	(Other)	☐
MULTIPLE COMPLETION	☒	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
CHANGE PLANS	☐		

17. PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of completion of work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and points pertinent to this work.) *

PROPOSE TO:

- (1) Pull 2" Tubing.
- (2) Set cement retainer @ 7700' & squeeze off Dakota Formation.
- (3) Perforate Mesaverde Formation & Sand/Water Frac.
- (4) Clean & Test Mesaverde Formation.
- (5) Set Bridge Plug above Mesaverde perforations.
- (6) Perforate Picture Cliff Formation & Sand/Water Frac.
- (7) Clean & Test Picture Cliff Formation.
- (8) Set production packer, run dual 1-1/2" Tubing strings & complete.



18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE District Superintendent DATE March 29, 1971
(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

44