

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
**BURLINGTON  
RESOURCES** OIL & GAS COMPANY

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
1600' FNL, 1090' FWL, Sec. 26, T-27-N, R-5-W, NMPM, Rio Arriba County

API # (assigned by OCD)  
30-039-20486

5. Lease Number  
Fee

6. State Oil & Gas Lease #  
Lease Name/Unit Name  
San Juan 27-5 Unit

8. Well No.  
134

9. Pool Name or Wildcat  
Tapacito Pict. Cliffs

10. Elevation:

**RECEIVED**  
JUN - 8 1999  
OIL CON. DIV.  
DIST. 3

Type of Submission	Type of Action
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other -
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Conversion to Injection

13. Describe Proposed or Completed Operations

5-14-99 MIRU. SD for weekend.

5-17-99 ND WH. NU BOP. Release Model "C-1" pkr. TOOH w/99 jts 1 1/4" tbq & pkr. TIH w/2 7/8" CIBP, set @ 3244'. TOOH. TIH to 3244'. Load hole & circ clean w/15 bbl wtr. PT csg to 500 psi, failed. Establish circ. Plug #1: pump 18 sx Class "B" neat cmt @ 2591-3243'. TOOH. WOC. TIH, tag TOC @ 2700'. PT csg to 500 psi, failed. Perf 3 sqz holes @ 1500'. TOOH. TIH w/cmt retainer, set @ 1465'. TIH, PT csg to 600 psi, failed. Establish injection. SDON.

5-18-99 Establish injection. Plug #2: pump 35 sx Class "B" neat cmt below cmt retainer outside csg @ 1400-1500'. Pump 5 sx Class "B" neat cmt above cmt retainer inside csg @ 1350-1465'. TOOH to 1267'. Circ hole clean w/8 bbl wtr. Reverse circ 1 bbl light colored cmt to surface. (Verbal approval to perf sqz holes @ 186' from Henry Villeneuve, OCD on location). TOOH. TIH, perf 3 sqz holes @ 186'. TOOH. Establish circ down 2 7/8" csg & out bradenhead. Plug #3: pump 69 sx Class "B" neat cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Pump 10 sx Class "B" neat cmt down 2 7/8" csg & 2 7/8" x 8 5/8" annulus. Install dry hole marker w/15 sx Class "B" neat cmt. WOC. RD. Rig released. Well plugged and abandoned 5-19-99. (Henry Villeneuve, OCD on location for plugging).

SIGNATURE [Signature] Regulatory Administrator June 4, 1999

no  
(This space for State Use)

ORIGINAL SIGNED BY E VILLANUEVA

DEPUTY OIL & GAS INSPECTOR, DIST. #8

JAN 18 2000

Approved by

Title

Date