

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Union Oil Company of California

3. Address and Telephone No.

3300 N. Butler, Ste 200, Farmington, NM 87401 (505) 326-7600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650' FSL & 1650' FWL  
Sec. 35, T27N R7W

5. Lease Designation and Serial No.

SF 080385

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

RINCON UNIT

8. Well Name and No.

193

9. API Well No.

30-039-20500

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

Rio Arriba,  
New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☒ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_
- ☒ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Sundry approval was received to perform a workover for casing repair utilizing the Guiberson Retrievable Casing Patch. Although the Casing Patch technique is believed to be a reliable permanent repair and successfully performed as such in other areas, the Sundry approval granted was a temporary approval requiring "permanent" repair after 3 years. Economics do not justify having to perform two repair workovers, therefore this Sundry is being submitted to repair the casing leak by squeeze cementing.

RECEIVED  
FEB 13 1992  
OIL CON. DIV.  
DIST. 2

14. I hereby certify that the foregoing is true and correct

Signed Craig A. [Signature]

Title Field Superintendent

Date APPROVED

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date FEB 11 1992

[Signature] AREA MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

NMOCD